

# DIN ISO 3951-1:2024-08 (E)

## Sampling procedures for inspection by variables - Part 1: Specification for single sampling plans indexed by acceptance quality limit (AQL) for lot-by-lot inspection for a single quality characteristic and a single AQL (ISO 3951-1:2022 )

---

Contents	Page
National foreword	4
National Annex NA (informative) Bibliography	5
Foreword	6
Introduction	7
<b>1 Scope</b>	<b>9</b>
<b>2 Normative references</b>	<b>9</b>
<b>3 Terms and definitions</b>	<b>10</b>
<b>4 Symbols</b>	<b>14</b>
<b>5 Choice of a sampling plan</b>	<b>15</b>
5.1 Choice between variables and attributes	15
5.2 General	16
5.3 Choice between the <i>s</i> -method and $\sigma$ -method	16
5.4 Choice of inspection level and AQL	17
<b>6 Standard procedures for the <i>s</i>-method</b>	<b>18</b>
6.1 General	18
6.2 Single specification limits	18
6.3 Double specification limits	19
<b>7 Standard procedures for the <math>\sigma</math>-method</b>	<b>19</b>
7.1 General	19
7.2 Single specification limits	19
7.3 Double specification limits	20
<b>8 The <i>p</i>*-method</b>	<b>20</b>
<b>9 Switching between inspection severities</b>	<b>21</b>
9.1 Rules for switching between inspection severities	22
9.2 Records for switching between inspection severities	23
<b>10 Relation to ISO 2859-1</b>	<b>23</b>
10.1 Similarities	23
10.2 Differences	24
<b>11 Allowing for measurement uncertainty</b>	<b>25</b>
<b>12 Normality, data transformations and outliers</b>	<b>25</b>
12.1 Normality	25
12.2 Data transformations	25
12.3 Outliers	26
<b>13 Monitoring and recording of inspection results</b>	<b>26</b>
13.1 Monitoring of inspection results	26
13.2 Process capability and performance assessment	26
13.3 Monitoring of process parameters	26
<b>14 Tables</b>	<b>27</b>
14.1 Form <i>k</i> for single sampling plans: <i>s</i> -method	27
14.2 Form <i>k</i> for single sampling plans: $\sigma$ -method	33

14.3	Form $p^*$ single sampling plans .....	39
14.4	Values of $f_\sigma$ for maximum process standard deviation (MPSD).....	45
14.5	Supplementary acceptance constants for qualifying towards reduced inspection .....	45
<b>15</b>	<b>Examples .....</b>	<b>46</b>
15.1	General.....	46
15.2	Examples for the $s$ -method.....	46
15.3	Examples for the $\sigma$ -method.....	53
15.4	Examples for the $p^*$ -method.....	57
<b>Annex A</b>	<b>(informative) Procedures for obtaining <math>s</math> and <math>\sigma</math>.....</b>	<b>60</b>
<b>Annex B</b>	<b>(informative) Accommodating measurement variability.....</b>	<b>63</b>
<b>Annex C</b>	<b>(informative) Sampling strategies .....</b>	<b>68</b>
<b>Annex D</b>	<b>(informative) Operating characteristics for the <math>\sigma</math>-method.....</b>	<b>70</b>
<b>Annex E</b>	<b>(informative) Operating characteristic for the <math>s</math>-method - tabulated values for single sampling plans, normal inspection.....</b>	<b>71</b>
<b>Annex F</b>	<b>(informative) Consumer's risk qualities.....</b>	<b>80</b>
<b>Annex G</b>	<b>(informative) Producer's risks.....</b>	<b>87</b>
<b>Annex H</b>	<b>(informative) Construction of acceptance diagrams for double specification limits.....</b>	<b>95</b>
<b>Annex I</b>	<b>(informative) Use of the underlying software.....</b>	<b>106</b>
<b>Bibliography</b>	<b>.....</b>	<b>111</b>