

ISO 7870-6:2024-07 (E)

Control charts - Part 6: EWMA control charts for the process mean

Contents		Page
Foreword.....		iv
Introduction.....		v
1 Scope		1
2 Normative references		1
3 Terms and definitions		1
4 Symbols and abbreviated terms		2
5 EWMA for inspection by variables		3
5.1 General.....		3
5.2 Weighted average explained.....		3
5.3 Control limits for EWMA control chart.....		4
5.4 Construction of EWMA control chart.....		5
5.5 Example.....		7
6 Choice of the control chart		10
6.1 Shewhart control chart versus EWMA control chart.....		10
6.2 Average run length.....		11
6.3 Choice of parameters for EWMA control chart.....		11
6.3.1 Choice of λ		11
6.3.2 Choice of L_z		12
6.3.3 Calculation for n		12
6.3.4 Example.....		13
7 Procedure for implementing the EWMA control chart		13
8 Sensitivity of the EWMA to non-normality		14
9 Advantages and limitations		14
9.1 Advantages.....		14
9.2 Limitations.....		14
Annex A (informative) Application of the EWMA control chart		16
Annex B (informative) EWMA control chart for a proportion of nonconforming items		20
Annex C (informative) EWMA control charts for a number of nonconformities		22
Bibliography		24