

# ISO 10725:2000-12 (E)

## Acceptance sampling plans and procedures for the inspection of bulk materials

---

<b>Contents</b>		<b>Page</b>
Foreword .....		vi
Introduction .....		vii
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>4</b>	<b>Symbols and abbreviated terms .....</b>	<b>3</b>
<b>5</b>	<b>Sampling plans .....</b>	<b>6</b>
5.1	General .....	6
5.2	Applicability .....	6
5.3	Standardized sampling procedures .....	7
5.4	Standard deviations .....	8
5.5	Costs .....	9
5.6	Acceptance quality limit and non-acceptance quality limit .....	10
5.7	Responsible authority .....	11
<b>6</b>	<b>Inspection procedures .....</b>	<b>12</b>
6.1	General .....	12
6.2	Assessment of the standard deviations .....	12
6.3	Determination of sample sizes .....	18
6.4	Selection and preparation of samples .....	21
6.5	Determination of the acceptance value .....	30
6.6	Determination of lot acceptability .....	31
<b>7</b>	<b>Examples .....</b>	<b>32</b>
7.1	Imprecise standard deviation with one-sided specification limit .....	32
7.2	Imprecise standard deviation with two-sided specification limits .....	33
7.3	Optional procedure for known standard deviation with one-sided specification limit .....	34
7.4	Known standard deviation with one-sided specification limit .....	35
7.5	Known standard deviations with two-sided specification limits .....	36
7.6	Revision of discrimination interval .....	38
7.7	Results from one lot .....	39
7.8	Results from consecutive lots .....	40
<b>Annex A (normative) Special procedures for inspecting multiple characteristics of a material .....</b>		<b>42</b>
<b>Annex B (normative) Acceptance sampling plans and procedures for use where the measurement standard deviation is dominant .....</b>		<b>47</b>
<b>Annex C (informative) Theoretical background .....</b>		<b>52</b>
<b>Annex D (informative) Operating characteristic curves .....</b>		<b>62</b>
<b>Bibliography .....</b>		<b>72</b>
<b>Figure 1 -- Schematic model of bulk acceptance sampling procedures .....</b>		<b>8</b>

Figure C.1 -- Relationship between mA, mR and acceptance value (Distribution of .....x ; lower specification limit) .....	55
Figure C.2 -- Relationship between mA, mR and acceptance value (Distribution of ..... x ; upper specification limit) .....	57
Figure C.3 -- Relationship between mAs, mRs and acceptance values (Distribution of ..... x ; two-sided specification limits) .....	57
Figure C.4 -- Relationship between D and D (when $D = d \pm D$ ) (Distribution of ..... x ; two-sided specification limits) .....	57
Figure D.1 -- OC curve for Example 1 .....	65
Figure D.2 -- OC curve for Example 2 .....	66
Figure D.3 -- OC curve for Example 3 .....	68
Figure D.4 -- OC curve for Example 4 .....	71
Table 1 -- Values of d for two-sided specification limits (imprecise standard deviations) .....	11
Table 2 -- Values of fU for UCL .....	15
Table 3 -- Sample sizes (a »»»» 5 %, b »»»» 10 %), cost ratio level 1 for RC »»»» 0,10 (0 to 0,17) .....	22
Table 4 -- Sample sizes (a »»»» 5 %, b »»»» 10 %), cost ratio level 2 for RC »»»» 0,32 (0,18 to 0,56) ..	22
Table 5 -- Sample sizes (a »»»» 5 %, b »»»» 10 %), cost ratio level 3 for RC »»»» 1,0 (0,57 to 1,7) .....	23
Table 6 -- Sample sizes (a »»»» 5 %, b »»»» 10 %), cost ratio level 4 for RC »»»» 3,2 (1,8 to 5,6) .....	23
Table 7 -- Sample sizes (a »»»» 5 %, b »»»» 10 %), cost ratio level 5 for RC »»»» 10 (5,7 or over) .....	24
Table 8 -- Sample sizes (a »»»» 5 %, b »»»» 5 %), cost ratio level 1 for RC »»»» 0,10 (0 to 0,17) .....	24
Table 9 -- Sample sizes (a »»»» 5 %, b »»»» 5 %), cost ratio level 2 for RC »»»» 0,32 (0,18 to 0,56) ....	25
Table 10 -- Sample sizes (a »»»» 5 %, b »»»» 5 %), cost ratio level 3 for RC »»»» 1,0 (0,57 to 1,7) .....	25
Table 11 -- Sample sizes (a »»»» 5 %, b »»»» 5 %), cost ratio level 4 for RC »»»» 3,2 (1,8 to 5,6) .....	26
Table 12 -- Sample sizes (a »»»» 5 %, b »»»» 5 %), cost ratio level 5 for RC »»»» 10 (5,7 or over) .....	26
Table 13 -- Sample sizes (a »»»» 5 %, b »»»» 5 %) and degrees of freedom for nM = 1, cost ratio level 1 for RC »»»» 0,10 (0 to 0,17) .....	27
Table 14 -- Sample sizes (a »»»» 5 %, b »»»» 5 %) and degrees of freedom for nM = 1, cost ratio level 2 for RC »»»» 0,32 (0,18 to 0,56) .....	27
Table 15 -- Sample sizes (a »»»» 5 %, b »»»» 5 %) and degrees of freedom for nM = 1, cost ratio level 3 for RC »»»» 1,0 (0,57 to 1,7) .....	28
Table 16 -- Sample sizes (a »»»» 5 %, b »»»» 5 %) and degrees of freedom for nM = 1, cost ratio level 4 for RC »»»» 3,2 (1,8 to 5,6) .....	28
Table 17 -- Sample sizes (a »»»» 5 %, b »»»» 5 %) and degrees of freedom for nM = 1, cost ratio level 5 for RC »»»» 10 (5,7 or over) .....	28

Table 18 -- Sample sizes (a »»»» 5 %, b »»»» 5 %) and degrees of freedom for nM = 2, cost ratio level 1 for RC »»»» 0,10 (0 to 0,17) .....	29
Table 19 -- Sample sizes (a »»»» 5 %, b »»»» 5 %) and degrees of freedom for nM = 2, cost ratio level 2 for RC »»»» 0,32 (0,18 to 0,56) .....	29
Table 20 -- Sample sizes (a »»»» 5 %, b »»»» 5 %) and degrees of freedom for nM = 2, cost ratio level 3 for RC »»»» 1,0 (0,57 to 1,7) .....	29
Table 21 -- Sample sizes (a »»»» 5 %, b »»»» 5 %) and degrees of freedom for nM = 2, cost ratio level 4 for RC »»»» 3,2 (1,8 to 5,6) .....	30
Table 22 -- Sample sizes (a »»»» 5 %, b »»»» 5 %) and degrees of freedom for nM = 2, cost ratio level 5 for RC »»»» 10 (5,7 or over) .....	30
Table 23 -- Data obtained from one lot .....	39
Table 24 -- Data of consecutive lots .....	41
Table A.1 -- Correction factor, fD, for J characteristics for known standard deviations .....	43
Table A.2 -- Risks at mA (a*) and at mR (b*) (for each of J characteristics, in %) .....	44
Table A.3 -- Correction factor, fD, for J characteristics for imprecise standard deviations .....	46
Table B.1 -- Sample sizes for special procedures (known standard deviations; a »»»» 5 %, b »»»» 10 %) .....	48
Table B.2 -- Sample sizes for special procedures (known standard deviations; a »»»» 5 %, b »»»» 5 %) .....	49
Table B.3 -- Sample sizes for special procedures (imprecise standard deviations; a »»»» 5 %, b »»»» 5 %) .....	49
Table D.1 -- OC values for Example 1 .....	65
Table D.2 -- OC values for Example 2 .....	67
Table D.3 -- OC values for Example 3, lower side .....	68
Table D.4 -- OC values for Example 3, upper side .....	68
Table D.5 -- OC values for Example 4 .....	70