

# ISO 1984-2:2001-06 (E)

## Test conditions for manually controlled milling machines with table of fixed height - Testing of the accuracy - Part 2: Machines with vertical spindle

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative reference .....</b>	<b>1</b>
<b>3</b>	<b>Terminology, designation of axes and machining operations carried out .....</b>	<b>1</b>
<b>3.1</b>	<b>Terminology and designation of axes .....</b>	<b>1</b>
<b>3.2</b>	<b>Machining operations carried out .....</b>	<b>1</b>
<b>4</b>	<b>Preliminary remarks .....</b>	<b>3</b>
<b>4.1</b>	<b>Measuring units .....</b>	<b>3</b>
<b>4.2</b>	<b>References to ISO 230-1 .....</b>	<b>3</b>
<b>4.3</b>	<b>Testing sequence .....</b>	<b>3</b>
<b>4.4</b>	<b>Tests to be performed .....</b>	<b>3</b>
<b>4.5</b>	<b>Measuring instruments .....</b>	<b>3</b>
<b>4.6</b>	<b>Machining test .....</b>	<b>4</b>
<b>4.7</b>	<b>Minimum tolerance .....</b>	<b>4</b>
<b>5</b>	<b>Geometric tests .....</b>	<b>5</b>
<b>5.1</b>	<b>Axes of motion .....</b>	<b>5</b>
<b>5.2</b>	<b>Table .....</b>	<b>8</b>
<b>5.3</b>	<b>Spindle .....</b>	<b>13</b>
<b>6</b>	<b>Machining test .....</b>	<b>16</b>
<b>Bibliography .....</b>		<b>17</b>