

# ISO 841:2001-10 (E)

## Industrial automation systems and integration - Numerical control of machines - Coordinate system and motion nomenclature

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Machine coordinate system .....</b>	<b>1</b>
4.1	Designation .....	1
4.2	Origin .....	2
4.3	Z axis .....	2
4.4	X axis .....	2
4.5	Y axis .....	3
4.6	Rotary axes A, B and C .....	3
<b>5</b>	<b>Principal machine motions .....</b>	<b>3</b>
5.1	Designation .....	3
5.2	Direction .....	3
<b>6</b>	<b>Additional motions .....</b>	<b>4</b>
6.1	Linear motions .....	4
6.2	Rotary motion .....	4
6.3	Letter restrictions .....	4
6.4	Direction .....	4
<b>7</b>	<b>Schematic drawings of machines .....</b>	<b>4</b>
7.1	Examples of machine drawings .....	4
7.2	Designation .....	5
<b>Annex A (normative)</b>	<b>Examples of machine motions .....</b>	<b>6</b>