

ISO/ASTM 52921:2013-06 (E)

Standard terminology for additive manufacturing - Coordinate systems and test methodologies

Contents		Page
1	Scope	1
2	Referenced Documents	1
3	Significance and Use	1
4	Terminology	1
5	Keywords	3
Annex		4
Figure A1.1 Generic (Upward Building) Additive Manufacturing Machine/System		4
Figure A1.2 Generic (Downward Building) Additive Manufacturing Machine/System		4
Figure A1.3 Right Hand Rule for Positive Rotations with Reference to the Build Volume Origin		5
Figure A1.4 Example of an Arbitrarily Oriented Minimum Bounding Box		5
Figure A1.5 Examples of Different Types of Bounding Boxes		6
Figure A1.6 Initial Build Orientation		7
Figure A1.7 Why is a Picture Normally Required to Communicate the Initial Build Orientation?		8
Figure A1.8 Orthogonal Orientation Notation		9
Figure A1.9 Examples of Bilateral Symmetry		10
Figure A1.10 Examples where Symmetry Allows Abbreviation of Orthogonal Orientation Notation ..		11
Figure A1.11 Part Location and Initial Build Orientation: Five Round Bar Specimens with Z Orientation		11
Figure A1.12 Part Location and Reorientation: Round Bars Oriented at B+45 from Z and B-45 from Z		12
Table A1.1 Description of Part Locations and Orientations		12
Table A1.2 Description of Part Locations and Orientations		12
Table X1.1 Task Group Contributors		13