

ISO/ASTM 52921:2013-06 (E)

Standard terminology for additive manufacturing - Coordinate systems and test methodologies

	Contents	Page
1	Scope	1
2	Referenced Documents	1
3	Significance and Use	1
4	Terminology	1
5	Keywords	3
	Annex	4
	Figure A1.1 Generic (Upward Building) Additive Manufacturing Machine/System	4
	Figure A1.2 Generic (Downward Building) Additive Manufacturing Machine/System	4
	Figure A1.3 Right Hand Rule for Positive Rotations with Reference to the Build Volume Origin	5
	Figure A1.4 Example of an Arbitrarily Oriented Minimum Bounding Box	5
	Figure A1.5 Examples of Different Types of Bounding Boxes	6
	Figure A1.6 Initial Build Orientation	7
	Figure A1.7 Why is a Picture Normally Required to Communicate the Initial Build Orientation?	8
	Figure A1.8 Orthogonal Orientation Notation	9
	Figure A1.9 Examples of Bilateral Symmetry	10
	Figure A1.10 Examples where Symmetry Allows Abbreviation of Orthogonal Orientation Notation ..	11
	Figure A1.11 Part Location and Initial Build Orientation: Five Round Bar Specimens with Z Orientation	11
	Figure A1.12 Part Location and Reorientation: Round Bars Oriented at B+45 from Z and B-45 from Z	12
	Table A1.1 Description of Part Locations and Orientations	12
	Table A1.2 Description of Part Locations and Orientations	12
	Table X1.1 Task Group Contributors	13