

DIN EN ISO/ASTM 52928:2024-10 (E)

Additive manufacturing of metals - Feedstock materials - Powder life cycle management (ISO/ASTM 52928:2024)

Contents		Page
European foreword.....		4
Foreword.....		5
Introduction.....		6
1	Scope	7
2	Normative references	7
3	Terms and definitions	7
4	Symbols and abbreviations	8
5	Powder properties	9
5.1	General.....	9
5.2	Particle size distribution.....	9
5.2.1	General.....	9
5.2.2	Dynamic image analysis.....	10
5.2.3	Laser diffraction and light scattering.....	10
5.2.4	Dry sieving.....	11
5.2.5	Light or scanning electron microscopy (SEM) images.....	11
5.3	Chemical composition.....	11
5.3.1	General.....	11
5.3.2	Combustion methods.....	12
5.3.3	Flame AAS.....	13
5.3.4	X-ray fluorescence spectroscopy (XRF).....	13
5.3.5	Inductively coupled plasma optical emission spectrometry (ICP-OES).....	13
5.3.6	Energy-dispersive X-ray spectroscopy (EDX).....	13
5.4	Characteristic densities.....	14
5.4.1	General.....	14
5.4.2	Apparent density.....	14
5.4.3	Tap density.....	14
5.4.4	Skeletal (true) density.....	14
5.4.5	Packing behaviour.....	14
5.5	Determination of powder density.....	15
5.5.1	Determination of the closed porosity of particles via indirect methods.....	15
5.5.2	Gas pycnometry.....	15
5.5.3	Metallographic section with porosity analysis.....	15
5.6	Shape and morphology.....	15
5.6.1	General.....	15
5.6.2	Image analysis.....	17
5.6.3	Scanning electron microscopy (SEM) images.....	17
5.6.4	Light microscopy images.....	18
5.6.5	Determination of specific surface area.....	18
5.7	Flowability.....	18
5.7.1	General.....	18
5.7.2	Determination of flow rate.....	19
5.7.3	Measuring the angle of repose.....	19
5.7.4	Ring shear test method.....	19
5.7.5	Rotating drum with dynamic image analysis.....	19
5.7.6	Powder rotational rheometer.....	19
5.7.7	Hausner ratio (ratio of tapped to bulk density).....	19

5.8	Contamination	20
5.8.1	Moisture content	20
5.8.2	Impurities	21
5.8.3	O/H content	21
5.8.4	N content	21
5.9	Absorption rate of the powder	21
5.9.1	General	21
5.9.2	Diffuse reflectance infrared Fourier transform (DRIFTS)	21
6	Powder life cycle	22
6.1	Batch requirement	22
6.1.1	General	22
6.1.2	Specification	22
6.1.3	Batch	22
6.1.4	Blend	22
6.1.5	Powder mix	22
6.1.6	Combine	22
6.1.7	Reuse metric	22
6.2	Traceability	23
6.2.1	General	23
6.2.2	Event history	23
6.2.3	Powder state	23
6.2.4	Labelling	23
6.3	Handling	24
6.3.1	General	24
6.3.2	Storage	24
6.3.3	Transfer	24
6.3.4	Repacking	25
6.4	Recycling/reuse of feedstock	25
6.5	Disposal	25
7	Powder quality assurance	26
7.1	Documentation requirements	26
7.2	Certificate of analysis (CoA)	26
7.3	Sampling	26
7.3.1	General remarks	26
7.3.2	Characterization of virgin powder and powder blends	27
7.3.3	Characterization of used powder	28
7.4	Powder analysis test methods	28
7.5	Monitoring and control of the environment	28
7.6	Test frequency	29
	Bibliography	30