

VEREIN
DEUTSCHER
INGENIEURE

Electrical Discharge Machining (EDM)
Definitions, processes, application

VDI 3400

Translation of the German issue 1975-06

The German version of this guideline shall be taken as authoritative. No guarantee can be given with respect to the English translation.

Contents	Page
Introduction.....	2
1 Definitions	2
1.1 Spark erosion (spark eroding, spark machining).....	2
1.2 Arc erosion (arc eroding, arc machining)	2
1.3 Machining methods based on spark erosion	2
1.4 Characteristic quantities.....	4
2 Spark-erosion machines	8
2.1 Configuration.....	8
2.2 Tool and workpiece	11
2.3 Characteristic data.....	11
2.4 Safety measures and regulations.....	11
2.5 Examples of actual spark-erosion machines	12
3 Application	12
3.1 General.....	12
3.2 Machinability of materials	14
3.3 Tool electrodes, manufacturing processes	14
3.4 Selection of the dielectric fluid	15
3.5 Application examples	16
Bibliography	24
Annex	25
Glossary	25
Safety measures for spark-erosion machines	26
Overview: Denotation of characteristic quantities	27

VDI Society for Production Engineering
(VDI-Gesellschaft Produktionstechnik – ADB)

VDI manual Production Management, Part 2: Manufacturing Processes
(VDI-Handbuch Betriebstechnik, Teil 2: Fertigungsverfahren)

Introduction

This guideline deals with the removal operations based on electro-discharge machining which are found in the bold-bordered boxes in Table 1. The guideline is the revision of the September 1970 issue of the guideline VDI 3400 and takes into account technical innovations and further developments in this field after that date.