

ISO 11665-6:2012-07 (E)

Measurement of radioactivity in the environment - Air: radon-222 - Part 6: Spot measurement method of the activity concentration

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms, definitions and symbols	1
3.1	Terms and definitions	1
3.2	Symbols	2
4	Principle	2
5	Equipment	2
6	Sampling	3
6.1	Sampling objective	3
6.2	Sampling characteristics	3
6.3	Sampling conditions	3
7	Detection	3
8	Measurement	4
8.1	Procedure	4
8.2	Influence quantities	4
8.3	Calibration	4
9	Expression of results	4
9.1	Radon activity concentration	4
9.2	Standard uncertainty	5
9.3	Decision threshold and detection limit	5
9.4	Limits of the confidence interval	5
10	Test report	5
Annex A (informative) Measurement method using scintillation cells		7
Bibliography		13