

# ISO 19581:2017-10 (E)

## Measurement of radioactivity - Gamma emitting radionuclides - Rapid screening method using scintillation detector gamma-ray spectrometry

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	2
4	Symbols and units .....	3
5	Principle .....	4
6	Apparatus .....	6
7	Sample container .....	7
8	Procedure .....	7
8.1	Packaging of samples for measuring purposes .....	7
8.2	Calibration .....	8
8.2.1	General .....	8
8.2.2	Reference source .....	8
8.2.3	Check source .....	8
8.2.4	Energy calibration .....	8
8.2.5	Detection efficiency calibration .....	9
8.3	Validation of the screening level .....	11
8.4	Screening procedure .....	11
8.4.1	Total spectrum counting / Single channel analyser counting .....	11
8.4.2	Multichannel analyser counting .....	12
8.4.3	Effect of sample density .....	13
9	Test report .....	13
Bibliography .....		18