

# ISO 11665-4:2020-01 (E)

## Measurement of radioactivity in the environment - Air: radon-222 - Part 4: Integrated measurement method for determining average activity concentration using passive sampling and delayed analysis

---

<b>Contents</b>	<b>Page</b>
Foreword .....	iv
Introduction .....	v
<b>1 Scope</b> .....	<b>1</b>
<b>2 Normative references</b> .....	<b>1</b>
<b>3 Terms, definitions and symbols</b> .....	<b>1</b>
3.1 Terms and definitions .....	1
3.2 Symbols .....	2
<b>4 Principle</b> .....	<b>2</b>
<b>5 Equipment</b> .....	<b>3</b>
<b>6 Sampling</b> .....	<b>3</b>
6.1 Sampling objective .....	3
6.2 Sampling characteristics .....	3
6.3 Sampling conditions .....	3
6.3.1 General .....	3
6.3.2 Installation of the sensor .....	3
6.3.3 Sampling duration .....	4
6.3.4 Volume of air sampled .....	4
<b>7 Detection</b> .....	<b>5</b>
<b>8 Measurement</b> .....	<b>5</b>
8.1 Procedure .....	5
8.2 Influence quantities .....	5
8.3 Calibration .....	5
<b>9 Expression of results</b> .....	<b>5</b>
9.1 Average radon activity concentration .....	5
9.2 Standard uncertainty .....	5
9.3 Decision threshold and detection limit .....	6
9.4 Limits of the confidence interval .....	6
<b>10 Test report</b> .....	<b>6</b>
<b>Annex A (informative) Measurement method using a solid-state nuclear track detector (SSNTD)</b> ..	<b>8</b>
<b>Annex B (informative) Measurement method using an electret detector</b> .....	<b>14</b>
<b>Annex C (informative) Measurement method using activated charcoal</b> .....	<b>22</b>
<b>Bibliography</b> .....	<b>31</b>