

IEC 62990-2:2021-06 (E)

Workplace atmospheres - Part 2: Gas detectors - Selection, installation, use and maintenance of detectors for toxic gases and vapours

Contents	Page
FOREWORD.....	4
INTRODUCTION.....	6
1 Scope.....	7
2 Normative references	7
3 Terms and definitions	7
4 Properties and detection of toxic gases and vapours	13
4.1 Properties and detection	13
4.2 The difference between detecting gases and vapours	14
4.3 Effects of water vapour on detection	17
4.4 Effects of temperature and pressure on detection	17
4.5 Effects of corrosion on detection.....	17
4.6 Detection by oxygen deficiency measurement.....	17
5 Measurement tasks	18
5.1 General.....	18
5.2 Exposure measurement (health monitoring)	18
5.3 General gas detection (safety monitoring).....	19
6 Selection of equipment	20
6.1 General.....	20
6.2 Performance and electrical tests	21
6.3 Indication range, measuring range and uncertainty of measurement	21
6.4 Selectivity requirements.....	22
6.5 The influence of environmental conditions	23
6.6 The influence of electromagnetic interference	23
6.7 Time of response and time of recovery	24
6.8 Time to alarm.....	25
6.9 Data logging	25
6.10 Instruction manual	26
7 Design and installation of fixed toxic gas detection equipment.....	26
7.1 General.....	26
7.2 Basic considerations for the installation of fixed systems	27
7.3 Location of detection points	28
7.4 Access for calibration and maintenance	33
7.5 Additional considerations for sample lines.....	33
7.6 Summary of considerations for the location of sensors or sampling points	34
7.7 Installation of sensors	35
7.8 Integrity and safety of fixed systems	35
7.9 Commissioning	36
7.10 Operating instructions, plans and records	37
8 Operation of toxic gas detection equipment	38
8.1 Alarm setting.....	38
8.2 Operation of portable equipment	39
8.3 Operation of transportable and fixed equipment	43
8.4 Sample lines and sampling probes	45
8.5 Accessories	45
9 Maintenance and calibration	46
9.1 General.....	46

9.2	Sensor	46
9.3	Flow systems of aspirated equipment.....	46
9.4	Readout devices	47
9.5	Alarms	47
9.6	Maintenance	47
9.7	Calibration	48
9.8	Operation test	49
9.9	Records	50
10	Training	50
10.1	General.....	50
10.2	Operator training.....	50
10.3	Maintenance and calibration training.....	51
Annex A (informative)	Commonly used measurement principles.....	52
A.1	General.....	52
A.2	Chemiluminescence	52
A.3	Colorimetry	53
A.4	Electrochemical	54
A.5	Flame-ionization	55
A.6	Gas chromatography.....	55
A.7	Infrared photometry	56
A.8	Ion mobility spectrometry	57
A.9	Mass spectrometry.....	58
A.10	Photo-ionization	59
A.11	Semiconductor	60
A.12	Ultra-violet/visible photometry	61
Bibliography	62
Figure 1	– Relationship between indication range and measuring range (See 6.3.1)	11
Figure 2	– Example of zero uncertainty	11
Figure 3	– Example of warm-up time in clean air.....	12
Figure 4	– Relationship between indication range and measuring range	22
Figure 5	– Gas response curves for test gas volume fractions of 40 ppm and 100 ppm	24
Figure 6	– Time to alarm at 25 ppm set point for test gas volume fractions of 40 ppm and 100 ppm.....	25
Table A.1	– Chemiluminescence	52
Table A.2	– Colorimetry	53
Table A.3	– Electrochemical	54
Table A.4	– Flame-ionization	55
Table A.5	– Infrared photometry.....	56
Table A.6	– Ion mobility spectrometry	57
Table A.7	– Mass spectrometry.....	58
Table A.8	– Photo-ionization (PID).....	59
Table A.9	– Semiconductor	60
Table A.10	– Ultra-violet/visible photometry	61