

ISO 4037-2:1997-12 (E)

X and gamma reference radiation for calibrating dosimeters and dose rate meters and for determining their response as a function of photon energy - Part 2: Dosimetry for radiation protection over the energy ranges 8 keV to 1,3 MeV and 4 MeV to 9 MeV

Contents		Page
1	Scope	1
2	Normative references	1
3	Definitions	2
4	Apparatus	4
5	General procedures	4
6	Procedures applicable to ionization chambers	6
7	Additional procedures and precautions specific to gamma radiation dosimetry using radionuclide sources	8
8	Additional procedures and precautions specific to X-radiation dosimetry	9
9	Special procedures and precautions specific to fluorescence X-radiation — Limitation of extraneous radiation in beams	11
10	Dosimetry of reference radiation at photon energies between 4 MeV and 9 MeV	11
11	Uncertainty of measurement	22
Annex A (informative) Determination by ionization chamber measurements of air kerma under receptor absent conditions and of absorbed dose to tissue (water) under receptor conditions		24
Annex B (informative) Bibliography		27