

ISO 6980-3:2006-10 (E)

Nuclear energy - Reference beta-particle radiation - Part 3: Calibration of area and personal dosimeters and the determination of their response as a function of beta radiation energy and angle of incidence

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	2
3	Terms and definitions	2
4	Procedures applicable to all area and personal dosimeters	9
4.1	General principles	9
4.2	Determination of the calibration factor and of the correction factor	12
5	Particular procedures for area dosimeters	13
5.1	General principles	13
5.2	Quantities to be measured	13
6	Particular procedures for personal dosimeters	13
6.1	General principles	13
6.2	Quantity to be measured	13
6.3	Experimental conditions	13
7	Presentation of results	15
7.1	Records and certificates	15
7.2	Statement of uncertainties	15
Annex A (normative) Symbols and abbreviated terms		17
Annex B (normative) Reference conditions		19
Annex C (informative) Conversion coefficients for some beta reference radiation fields		21
Bibliography		23