

# DIN EN ISO 16120-1:2011-10 (E)

## Non-alloy steel wire rod for conversion to wire - Part 1: General requirements (ISO16120-1:2011)

---

Contents	Page
<b>Foreword.....</b>	<b>3</b>
1 <b>Scope .....</b>	<b>4</b>
2 <b>Normative references .....</b>	<b>4</b>
3 <b>Terms and definitions .....</b>	<b>5</b>
4 <b>Classification.....</b>	<b>5</b>
5 <b>Ordering information to be supplied by the purchaser .....</b>	<b>6</b>
6 <b>Production process .....</b>	<b>7</b>
7 <b>Requirements .....</b>	<b>7</b>
7.1 <b>General.....</b>	<b>7</b>
7.2 <b>Quality system .....</b>	<b>7</b>
7.3 <b>Method of delivery .....</b>	<b>7</b>
7.4 <b>Delivery condition.....</b>	<b>7</b>
8 <b>Dimensions, mass and tolerances.....</b>	<b>7</b>
9 <b>Inspection .....</b>	<b>7</b>
9.1 <b>Inspection and inspection documents .....</b>	<b>7</b>
9.2 <b>Extension of inspection .....</b>	<b>8</b>
9.3 <b>Acceptance unit, number of samples and test pieces.....</b>	<b>8</b>
9.4 <b>Sampling and preparation of samples and test pieces .....</b>	<b>9</b>
9.5 <b>Test methods.....</b>	<b>9</b>
9.6 <b>Retest .....</b>	<b>10</b>
10 <b>Marking .....</b>	<b>10</b>
11 <b>Disputes .....</b>	<b>10</b>
<b>Annex A (normative) Determination of core segregation .....</b>	<b>11</b>
<b>Annex B (informative) Measurement of surface discontinuities .....</b>	<b>14</b>
<b>Annex C (informative) Mechanical damage .....</b>	<b>17</b>
<b>Annex D (normative) Determining the percentage of resolvable pearlite .....</b>	<b>22</b>
<b>Bibliography .....</b>	<b>24</b>