

# ISO 877-2:2009-06 (E)

## Plastics - Methods of exposure to solar radiation - Part 2: Direct weathering and exposure behind window glass

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
1	<b>Scope .....</b>	<b>1</b>
2	<b>Normative references .....</b>	<b>1</b>
3	<b>Principle .....</b>	<b>1</b>
4	<b>Apparatus .....</b>	<b>1</b>
5	<b>Test specimens .....</b>	<b>3</b>
6	<b>Conditions of exposure of the test specimens .....</b>	<b>4</b>
7	<b>Exposure stages .....</b>	<b>4</b>
8	<b>Procedure .....</b>	<b>5</b>
9	<b>Expression of results .....</b>	<b>6</b>
10	<b>Test report .....</b>	<b>6</b>