

DIN EN 16795:2016-03 (E)

Plastics - Method for estimating heat build up of flat surfaces by simulated solar radiation

Contents		Page
European foreword		3
Introduction		4
1	Scope	5
2	Normative references	5
3	Terms and definitions	5
4	Abbreviations	5
5	Principle	5
6	Apparatus	6
6.1	General	6
6.2	Test chamber	6
6.3	Laboratory radiation source	6
6.4	Radiometer	7
6.5	Test chamber temperature and relative humidity	7
6.6	Surface temperature measurement device	7
6.7	Black and white standard thermometer	8
6.8	Defined airflow directed across the sample	9
6.9	Specimen holders	9
7	Test specimens	9
7.1	Form, shape and preparation	9
7.2	Number of test specimens	9
8	Exposure conditions	9
8.1	Radiation	9
8.2	Black and white standard thermometer	9
8.3	Chamber air temperature	10
8.4	Relative humidity of chamber air	10
8.5	Wind speed	10
8.6	Sets of exposure conditions	10
9	Procedure	10
9.1	General	10
9.2	Mounting the test specimens	10
9.3	Exposure	10
9.4	Measurement of the surface temperature	11
10	Test report	11
Bibliography		12