

# ISO 13802:2015-06 (E)

## Plastics - Verification of pendulum impact-testing machines - Charpy, Izod and tensile impact-testing

---

<b>Contents</b>		<b>Page</b>
Foreword .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>4</b>	<b>Measurement instruments .....</b>	<b>4</b>
<b>5</b>	<b>Description of a pendulum impact-testing machine .....</b>	<b>4</b>
5.1	Types of pendulum impact-testing machines .....	4
5.2	Testing machine components .....	4
5.2.1	Machine frame -- The base of the machine and the structure supporting the pendulum .....	4
5.2.2	Pendulum .....	4
5.2.3	Test specimen anvils, supports, clamps and/or holders .....	5
5.2.4	Indicating equipment for absorbed energy (e.g. scale and friction pointer or electronic readout device) .....	5
<b>6</b>	<b>Procedure for verification and inspection of a pendulum impact-testing machine .....</b>	<b>5</b>
6.1	Certification of machine design and manufacturer .....	5
6.2	Field verification of the machine frame shall consist of determining the following items (see Table 4) .....	6
6.2.1	Installation .....	6
6.2.2	Levelness .....	6
6.2.3	Axial play of the pendulum bearings .....	6
6.2.4	Radial play of the pendulum bearings .....	6
6.2.5	Mechanism for holding and releasing the pendulum .....	6
6.2.6	Free hanging position .....	6
6.2.7	Contact between specimen and striking edge (Izod/Charpy) .....	6
6.2.8	Potential energy, E .....	7
6.2.9	Pendulum length, LP .....	8
6.2.10	Impact length, L .....	9
6.2.11	Velocity of the pendulum at instant of impact, v, .....	9
6.3	Charpy testing machines .....	10
6.4	Izod testing machines .....	11
6.4.1	Line of contact of the striker .....	11
6.4.4	Location of specimen and striker .....	12
6.4.5	Vice faces .....	12
6.5	Tensile impact testing machines (see ISO 8256) .....	12
6.5.1	Specimen clamps for tensile impact test machines .....	12
6.5.2	Clamps for tensile impact testing .....	13
6.5.3	Alignment .....	13
6.5.4	Mass of crosshead .....	13
6.6	Energy indicating system .....	13
6.6.1	Types of scale .....	13
6.6.2	Verification of analogue indicating equipment shall consist of the following examinations .....	14
6.6.3	Error in the indicated absorbed energy, $W_i$ , on analogue indicating systems .....	14
6.6.4	Verification of digital indicating equipment shall ensure that the following requirements are met .....	14

<b>6.7</b>	<b>Losses due to friction .....</b>	<b>15</b>
<b>6.7.1</b>	<b>Types of loss .....</b>	<b>15</b>
<b>6.7.2</b>	<b>Determination of the loss due to friction in the pointer .....</b>	<b>15</b>
<b>6.7.3</b>	<b>Determination of losses due to air resistance and friction in the pendulum bearings .....</b>	<b>15</b>
<b>6.7.4</b>	<b>Calculation of the total energy lost due to friction .....</b>	<b>15</b>
<b>6.7.5</b>	<b>Maximum permissible losses due to friction .....</b>	<b>16</b>
<b>7</b>	<b>Frequency of verification .....</b>	<b>17</b>
<b>8</b>	<b>Verification report .....</b>	<b>18</b>
<b>Annex A (normative)</b>	<b>Design requirements for Charpy machines .....</b>	<b>19</b>
<b>Annex B (normative)</b>	<b>Design requirements for Izod machines .....</b>	<b>21</b>
<b>Annex C (normative)</b>	<b>Design requirements for tensile impact machines .....</b>	<b>23</b>
<b>Annex D (informative)</b>	<b>Ratio of frame mass to pendulum mass .....</b>	<b>26</b>
<b>Annex E (informative)</b>	<b>Deceleration of pendulum during impact .....</b>	<b>29</b>
<b>Annex F (informative)</b>	<b>Gauge plate for verification of Charpy impact pendulums .....</b>	<b>31</b>