

# ISO 2818:2018-12 (E)

## Plastics - Preparation of test specimens by machining

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Test specimens .....</b>	<b>5</b>
<b>4.1</b>	<b>Shape and state of the test specimens .....</b>	<b>5</b>
<b>4.2</b>	<b>Preparation of test specimens .....</b>	<b>6</b>
<b>5</b>	<b>Machinery and tools .....</b>	<b>6</b>
<b>5.1</b>	<b>General .....</b>	<b>6</b>
<b>5.2</b>	<b>Milling cutters .....</b>	<b>6</b>
<b>5.3</b>	<b>Slicing or sawing machines .....</b>	<b>6</b>
<b>5.4</b>	<b>Tubular cutting machines .....</b>	<b>6</b>
<b>5.5</b>	<b>Lathes .....</b>	<b>7</b>
<b>5.6</b>	<b>Planing machines .....</b>	<b>7</b>
<b>5.7</b>	<b>Stamping tools .....</b>	<b>7</b>
<b>5.8</b>	<b>Broaching tools .....</b>	<b>7</b>
<b>6</b>	<b>Procedure .....</b>	<b>7</b>
<b>6.1</b>	<b>General .....</b>	<b>7</b>
<b>6.2</b>	<b>Preparation of dumb-bell specimens .....</b>	<b>7</b>
<b>6.3</b>	<b>Preparation of rectangular test specimens by sawing or cutting with an abrasive disc .....</b>	<b>7</b>
<b>6.4</b>	<b>Preparation of disc-shaped test specimens .....</b>	<b>7</b>
<b>6.5</b>	<b>Stamping out test specimens of any shape .....</b>	<b>8</b>
<b>6.6</b>	<b>Notching finished test specimens by milling or broaching .....</b>	<b>8</b>
<b>7</b>	<b>Test report .....</b>	<b>9</b>
<b>Bibliography .....</b>		<b>16</b>