

# ISO 1183-1:2019 (E)

## Plastics — Methods for determining the density of non-cellular plastics — Part 1: Immersion method, liquid pycnometer method and titration method

---

### Contents

	Foreword
1	Scope
2	Normative references
3	Terms and definitions
4	Conditioning
5	Methods
5.1	Method A — Immersion method
5.1.1	Apparatus
5.1.2	Immersion liquid
5.1.3	Specimens
5.1.4	Procedure
5.2	Method B — Liquid pycnometer method
5.2.1	Apparatus
5.2.2	Immersion liquid
5.2.3	Specimens
5.2.4	Procedure
5.3	Method C — Titration method
5.3.1	Apparatus
5.3.2	Immersion liquids
5.3.3	Specimens
5.3.4	Procedure
6	Correction for buoyancy in air
7	Test report
Annex A	(informative) Liquid systems suitable for use in Method C
Annex B	(informative) Correction for buoyancy in air

Page count: 12