

# ISO 11357-2:2020-03 (E)

## Plastics - Differential scanning calorimetry (DSC) - Part 2: Determination of glass transition temperature and step height

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Principle .....	1
5	Apparatus and materials .....	2
6	Test specimens .....	2
7	Test conditions and specimen conditioning .....	2
8	Calibration .....	2
9	Procedure .....	2
9.1	Setting up the apparatus .....	2
9.2	Loading the test specimen into the crucible .....	2
9.3	Insertion of crucibles .....	2
9.4	Temperature scan .....	2
10	Expression of results .....	3
10.1	Determination of glass transition temperatures .....	3
10.1.1	General .....	3
10.1.2	Equal-areas method .....	4
10.1.3	Half-step-height method .....	6
10.1.4	Inflection-point method .....	7
10.2	Determination of glass transition step height .....	8
11	Precision .....	8
12	Test report .....	8
Bibliography .....		9