

# ISO/TS 4767:2024-01 (E)

## Plastics - Method of exposure to electrodeless plasma radiation sources

---

### Contents

Page

<b>Foreword</b> .....	<b>iv</b>
<b>1 Scope</b> .....	<b>1</b>
<b>2 Normative references</b> .....	<b>1</b>
<b>3 Terms and definitions</b> .....	<b>1</b>
<b>4 Principle</b> .....	<b>1</b>
<b>5 Apparatus</b> .....	<b>2</b>
5.1 Laboratory radiation source.....	2
5.1.1 General.....	2
5.1.2 Spectral irradiance of electrodeless plasma lamps.....	2
5.1.3 Irradiance uniformity.....	2
5.2 Test chamber.....	2
5.3 Radiometer.....	2
5.4 Black-panel thermometer.....	3
5.5 Specimen holders.....	3
<b>6 Test specimens</b> .....	<b>3</b>
<b>7 Exposure conditions</b> .....	<b>3</b>
7.1 Radiation.....	3
7.2 Temperature.....	3
<b>8 Procedure</b> .....	<b>3</b>
8.1 General.....	3
8.2 Mounting the test specimens.....	3
8.3 Exposure.....	4
8.4 Measurement of radiant exposure.....	4
8.5 Determination of changes in properties after exposure.....	4
<b>9 Test report</b> .....	<b>4</b>
<b>Annex A (informative) Spectral irradiance of electrodeless plasma lamps</b> .....	<b>5</b>
<b>Bibliography</b> .....	<b>6</b>