

ISO 15166-2:2000-12 (E)

Adhesives - Methods for preparing bulk specimens - Part 2: Elevated-temperature-curing one-part systems

Contents		Page
1	Scope	1
2	Normative references	1
3	Mould description	1
4	Dispensing the adhesive	2
5	Moulding	4
6	Curing	4
7	Specimen preparation report	4