

# ISO 877-2:2025-07 (E)

## Plastics - Methods of exposure to solar radiation - Part 2: Direct weathering and exposure behind window glass

---

### Contents

Page

Foreword.....	iv
<b>1</b> <b>Scope</b> .....	<b>1</b>
<b>2</b> <b>Normative references</b> .....	<b>1</b>
<b>3</b> <b>Terms and definitions</b> .....	<b>1</b>
<b>4</b> <b>Principle</b> .....	<b>1</b>
<b>5</b> <b>Apparatus</b> .....	<b>1</b>
5.1    General requirements.....	1
5.2    Test fixture for exposures using method A.....	2
5.3    Test fixture for exposures using method B.....	2
5.4    Apparatus for measurement of climatic factors.....	3
<b>6</b> <b>Test specimens</b> .....	<b>3</b>
<b>7</b> <b>Conditions of exposure of the test specimens</b> .....	<b>4</b>
7.1    Exposure aspect.....	4
7.2    Exposure site.....	4
<b>8</b> <b>Exposure stages</b> .....	<b>4</b>
8.1    General.....	4
8.2    Duration of exposure.....	4
8.3    Solar radiant exposure.....	5
<b>9</b> <b>Procedure</b> .....	<b>5</b>
9.1    Mounting of test specimens.....	5
9.1.1    General.....	5
9.1.2    Method A.....	5
9.1.3    Method B.....	5
9.2    Mounting of reference materials (if used).....	5
9.3    Climatic observations.....	5
9.4    Exposure of test specimens.....	5
9.4.1    General.....	5
9.4.2    Method A.....	5
9.4.3    Method B.....	5
9.5    Determination of changes in properties.....	6
<b>10</b> <b>Expression of results</b> .....	<b>6</b>
10.1    Determination of changes in properties.....	6
10.2    Climatic conditions.....	6
<b>11</b> <b>Test report</b> .....	<b>6</b>
<b>Bibliography</b> .....	<b>7</b>