

ISO 877-3:2026-05 (E)

Plastics - Methods of exposure to solar radiation - Part 3: Intensified weathering using concentrated solar radiation

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	1
5	Apparatus	2
5.1	General requirements	2
5.2	Apparatus for measurement of climatic factors	3
6	Test specimens	3
7	Exposure conditions	4
7.1	Orientation of mirrors	4
7.2	Exposure site	4
7.3	Temperature control	4
7.4	Irradiance level	5
8	Exposure stages	6
8.1	General	6
8.2	Solar radiant exposure	6
8.2.1	Guidance for selection of the exposure stage	6
8.2.2	Instrumental measurement of solar radiant exposure	6
9	Procedure	7
9.1	Mounting of test specimens	7
9.2	Mounting of reference materials (if used)	7
9.3	Climatic observations	7
9.4	Exposure of test specimens	7
9.4.1	General	7
9.4.2	Exposure cycles	7
9.4.3	Testing under glass	7
10	Expression of results	8
10.1	Determination of changes in properties	8
10.2	Climatic conditions and observations	8
10.2.1	General	8
10.2.2	Temperature	8
10.2.3	Relative humidity	8
10.2.4	Levels (values) of exposure stages	8
10.2.5	Radiation measurement	9
10.2.6	Precipitation	9
10.2.7	Time of wetness	9
10.2.8	Other observations	9
11	Test report	9
Bibliography		10