

# ISO 1183-1:2004-02 (E)

## Plastics - Methods for determining the density of non-cellular plastics - Part 1: Immersion method, liquid pycnometer method and titration method

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b> .....		<b>iv</b>
<b>1</b>	<b>Scope</b> .....	<b>1</b>
<b>2</b>	<b>Normative references</b> .....	<b>1</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>2</b>
<b>4</b>	<b>Conditioning</b> .....	<b>2</b>
<b>5</b>	<b>Methods</b> .....	<b>3</b>
<b>5.1</b>	<b>Method A -- Immersion method</b> .....	<b>3</b>
<b>5.2</b>	<b>Method B -- Liquid pycnometer method</b> .....	<b>5</b>
<b>5.3</b>	<b>Method C -- Titration method</b> .....	<b>6</b>
<b>6</b>	<b>Correction for buoyancy in air</b> .....	<b>7</b>
<b>7</b>	<b>Test report</b> .....	<b>8</b>
<b>Annex A (informative) Liquid systems suitable for use in Method C</b> .....		<b>9</b>