

ISO 11402:2004-03 (E)

Phenolic, amino and condensation resins - Determination of free-formaldehyde content

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Test procedures	2
4.1	General	2
4.2	Hydroxylamine hydrochloride procedure	2
4.3	Sulfite procedure	4
4.4	KCN procedure	7
5	Test report	10
Annex A (informative) Suitability of the procedures for different types of resin		11
Annex B (informative) Removal of Hg²⁺ and CN⁻ from mercury and cyanide residues		12