

DIN EN ISO 4892-3:2006-05 (E)

Plastics - Methods of exposure to laboratory light sources - Part 3: Fluorescent UV lamps (ISO 4892-3:2006)

Contents		Page
Foreword		2
1	Scope	4
2	Normative references	4
3	Principle	4
4	Apparatus	5
4.1	Laboratory light source	5
4.2	Test chamber	8
4.3	Radiometer	8
4.4	Black-standard/black-panel thermometer	8
4.5	Wetting and humidity	8
4.6	Specimen holders	9
4.7	Apparatus to assess changes in properties	9
5	Test specimens	9
6	Test conditions	9
6.1	Radiation	9
6.2	Temperature	9
6.3	Relative humidity of chamber air	10
6.4	Condensation and spray cycles	10
6.5	Cycles with dark periods	10
6.6	Sets of exposure conditions	10
7	Procedure	11
7.1	General	11
7.2	Mounting the test specimens	11
7.3	Exposure	12
7.4	Measurement of radiant exposure	12
7.5	Determination of changes in properties after exposure	12
8	Exposure report	12
Annex A (informative) Spectral distribution of radiation for typical fluorescent UV lamps		13
Bibliography		17