

ISO 8988:2006-09 (E)

Plastics - Phenolic resins - Determination of hexamethylenetetramine content - Kjeldahl method, perchloric acid method and hydrochloric acid method

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Kjeldahl method	1
4	Perchloric acid method	3
5	Hydrochloric acid method	5
6	Test report	7