

DIN EN 13999-2:2007-07 (E)

Adhesives - Short term method for measuring the emission properties of low-solvent or solvent-free adhesives after application - Part 2: Determination of volatile organic compounds

Contents		Page
Foreword		3
SAFETY STATEMENT		4
1 Scope		4
2 Normative references		4
3 Principle		4
4 Reagents and materials		5
5 Apparatus		5
6 Procedure		6
7 Identification and calculation		9
8 Precision and bias		11
9 Test report		11
10 Quality control		12
Bibliography		13