

DIN EN 16117-1:2011-12 (E)

Copper and copper alloys - Determination of copper content - Part 1: Electrolytic determination of copper in materials with copper content less than 99,85 %

Contents		Page
Foreword		3
1	Scope	4
2	Normative references	4
3	Principle	4
4	Reagents	4
5	Apparatus	5
6	Sampling	5
7	Procedure	5
7.1	Test portion	5
7.2	Determination	5
8	Expression of results	6
9	Precision	6
10	Test report	7
Annex A (normative)	Spent electrolyte -- Determination of residual copper -- Flame atomic absorption spectrometric method (FAAS)	8
A.1	General	8
A.2	Principle	8
A.3	Reagents	8
A.4	Apparatus	9
A.5	Procedure	9
A.6	Expression of results	10
Bibliography		12