

DIN EN 15024-2:2018-06 (E)

Copper and copper alloys - Determination of zinc content - Part 2: Flame atomic absorption spectrometric method (FAAS)

Contents		Page
European foreword		3
1	Scope	4
2	Normative references	4
3	Principle	4
4	Reagents	4
5	Apparatus	5
6	Sampling	5
7	Procedure	5
7.1	Preparation of the test portion solution	5
7.2	Blank test	6
7.3	Check test	6
7.4	Establishment of the calibration curve	7
7.5	Determination	9
8	Expression of results	10
8.1	Use of the calibration curve	10
8.2	Use of bracketing method	11
9	Precision	11
10	Test report	13
Bibliography		14