

# DIN EN 15022-3:2006-12 (E)

## Copper and copper alloys - Determination of tin content - Part 3: Low tin content - Flame atomic absorption spectrometry method (FAAS)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
1	Scope .....	4
2	Normative references .....	4
3	Principle .....	4
4	Reagents and materials .....	4
5	Apparatus .....	5
6	Sampling .....	5
7	Procedure .....	6
8	Expression of results .....	8
9	Precision .....	9
10	Test report .....	10
Bibliography .....		11