

# ISO 12744:2006-04 (E)

## Copper, lead, zinc and nickel concentrates - Experimental methods for checking the precision of sampling

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>General conditions .....</b>	<b>1</b>
3.1	General .....	1
3.2	Number of lots .....	1
3.3	Number of increments and number of samples .....	1
3.4	Sample processing and analysis .....	2
3.5	Frequency of precision checks .....	2
<b>4</b>	<b>Symbols .....</b>	<b>2</b>
<b>5</b>	<b>Method of experiment .....</b>	<b>3</b>
5.1	Interleaved samples .....	3
5.2	Sample processing and analysis .....	3
5.2.1	Sample processing method 1 (see Figure 2) .....	3
5.2.2	Sample processing method 2 (see Figure 3) .....	3
5.2.3	Sample processing method 3 (see Figure 4) .....	3
<b>6</b>	<b>Evaluation of experimental data .....</b>	<b>6</b>
6.1	General .....	6
6.2	Sample processing method 1 .....	6
6.3	Sample processing method 2 .....	8
6.4	Sample processing method 3 .....	9
<b>7</b>	<b>Assessment of results and action .....</b>	<b>11</b>
7.1	Primary sampling .....	11
7.2	Sample processing .....	11
7.3	Analysis .....	11
<b>8</b>	<b>Recording of data .....</b>	<b>11</b>
<b>Annex A (informative)</b>	<b>Recording of sampling data .....</b>	<b>12</b>
<b>Bibliography .....</b>		<b>15</b>