

ISO/TS 13399-303:2016-02 (E)

Cutting tool data representation and exchange - Part 303: Creation and exchange of 3D models - Solid end mills

Contents	Page
Foreword	v
Introduction	vii
1 Scope	1
2 Normative references	1
3 Starting elements, coordinate systems, planes	2
3.1 General	2
3.2 Reference system	2
3.3 Coordinate system at the cutting part	3
3.4 Planes	3
3.5 Cutting reference point (CRP)	4
4 Design of the model	5
4.1 General	5
4.2 Necessary parameters for the connection interface feature	5
5 Non-centre cutting end mill	5
5.1 General	5
5.2 Necessary properties	6
5.3 Geometry of the non-cutting part inclusive of the connection	7
5.4 Geometry of the cutting part	7
5.5 Complete non-centre cutting end mill	8
6 Centre cutting end mill	9
6.1 General	9
6.2 Necessary properties	9
6.3 Geometry of the non-cutting part inclusive of the connection	9
6.4 Geometry of the cutting part	10
6.5 Complete centre cutting end mill	10
7 Angular end mill (V-groove)	11
7.1 General	11
7.2 Necessary properties	11
7.3 Geometry of the non-cutting part inclusive of the connection	11
7.4 Geometry of the cutting part	12
7.5 V-groove end mill, complete	13
8 Dovetail end mill	13
8.1 General	13
8.2 Necessary properties	13
8.3 Geometry of the non-cutting part inclusive of the connection	13
8.4 Geometry of the cutting part	14
8.5 Complete dovetail end mill, complete	15
9 T-slot end mill	15
9.1 General	15
9.2 Necessary properties	15
9.3 Geometry of the non-cutting part inclusive of the connection	15

9.4	Geometry of the cutting part	16
9.5	Complete T-slot end mill	16
10	Ball-nosed end mill	17
10.1	General	17
10.2	Necessary properties	17
10.3	Geometry of the non-cutting part inclusive of the connection	18
10.4	Geometry of the cutting part	18
10.5	Complete ball-nosed end mill	18
11	Die end mill	19
11.1	General	19
11.2	Necessary properties	19
11.3	Geometry of the non-cutting part inclusive of the connection	20
11.4	Geometry of the cutting part	20
11.5	Complete die end mill	20
12	Concaverooundedprofileendmill	21
12.1	General	21
12.2	Necessary properties	21
12.3	Geometry of the non-cutting part inclusive of the connection	21
12.4	Geometry of the cutting part	21
12.5	Complete concave rounded profile end mill	22
13	Thread end mill	23
13.1	General	23
13.2	Necessary properties	23
13.3	Geometry of the non-cutting part inclusive of the connection	24
13.4	Geometry of the cutting part	24
13.5	Complete thread end mill	24
14	Cutting stylus	25
14.1	General	25
14.2	Necessary properties	25
14.3	Geometry of the non-cutting part inclusive of the connection	26
14.4	Geometry of the cutting part	26
14.5	Complete cutting stylus, complete	26
15	Thread end mill with drilling part	27
15.1	General	27
15.2	Necessary properties	27
15.3	Geometry of the non-cutting part inclusive of the connection	28
15.4	Geometry of the cutting part	28
15.5	Complete thread end mill with drilling part	28
16	Design of details	29
16.1	Basics for modelling	29
16.2	Contact/clamping surfaces -- Orientation	29
16.3	Chamfers, rounding, others	29
17	Attributes of surfaces -- Visualization of the model features	29
18	Structure of the design elements (tree of model)	30
19	Data exchange model	30
	Annex A (informative) Information about nominal dimensions	32
	Bibliography	33