

ISO/TS 13399-312:2016-02 (E)

Cutting tool data representation and exchange - Part 312: Creation and exchange of 3D models - Reamers for indexable inserts

Contents		Page
Foreword		v
Introduction		vii
1	Scope	1
2	Normative references	1
3	Starting elements, coordinate systems, planes	2
3.1	General	2
3.2	Reference system	2
3.3	Primary coordinate system and mounting coordinate system	2
3.4	Coordinate system at the cutting part	3
3.5	Planes	3
3.6	Design of the pocket seat and cutting reference point (CRP) of the insert	4
3.7	Adjustment coordinate system on workpiece side	6
3.7.1	General	6
3.7.2	Designation of the coordinate system workpiece side	6
4	Design of the model	7
4.1	General	7
4.2	Necessary parameters for the connection interface feature	8
4.3	Necessary properties for inserts	8
4.3.1	General	8
4.3.2	Properties of inserts for reaming operations	9
4.3.3	Design of the pocket seat feature	9
5	Cylindrical reamer	9
5.1	General	9
5.2	Necessary properties	10
5.3	Basic geometry	11
5.4	Determination of the position of the mounting coordinate system of insert	11
5.5	Chip flute and pocket seat	12
5.6	Cylindrical reamer -- Assembly	13
6	Tapered reamer	14
6.1	General	14
6.2	Necessary properties	14
6.3	Basic geometry	15
6.4	Determination of the position of the mounting coordinate system of insert	15
6.5	Chip flute and pocket seat	16
6.6	Tapered reamer, assembled	17
7	Stepped(profile)reamer	17
7.1	General	17
7.2	Necessary properties	18
7.3	Basic geometry	19
7.4	Determination of the position of the mounting coordinate system of insert	20
7.5	Chip flute and pocket seat	21
7.6	Assembled stepped (profile) reamer	23

8	Bell style reamer	23
8.1	General	23
8.2	Necessary properties	24
8.3	Basic geometry	25
8.4	Determination of the position of the mounting coordinate system of insert	26
8.5	Chip flute and pocket seats	28
8.6	Assembled bell style reamer	29
9	Shell reamer	29
9.1	General	29
9.2	Necessary properties	30
9.3	Basic geometry	30
9.4	Determination of the position of the mounting coordinate system of insert	31
9.5	Chip flute and pocket seats	32
9.6	Assembled shell reamer	33
10	Design of details	34
10.1	Basics for modelling	34
10.2	Contact/clamping surfaces -- Orientation	34
10.3	Chamfers and roundings	35
11	Attributes of surfaces -- Visualization of the model features	35
12	Structure of the design elements (tree of model)	35
13	Data exchange model	36
	Annex A (informative) Information about nominal dimensions	38
	Bibliography	39