

ISO/TS 13399-70:2016-07 (E)

Cutting tool data representation and exchange - Part 70: Graphical data layout - Layer setting for tool layout

Contents		Page
Foreword		iv
Introduction		vi
1	Scope	1
2	Terms and definitions	1
3	Layer concept	4
4	Structure of the layers	5
4.1	General	5
4.2	Colouring of the layers	5
4.3	Grouping and definition of the layers	6
4.3.1	Grouping	6
4.3.2	Basic layer	6
4.3.3	Tool drawing (main view -- function number 3.0.1)	6
4.3.4	NC-Geometry (CUT, NOCUT -- function number 3.0.2)	8
4.3.5	Extended tool drawing (further views -- function number 3.0.3)	9
4.3.6	Multilingual (global drawing -- function number 3.0.4)	10
4.3.7	Tool reconditioning (supplier specific information -- function number 3.0.5)	12
4.3.8	Machine equipment layout (machining processes -- function number 3.0.6)	13
4.3.9	Drawing frame (multilingual and drawing space -- function number 3.0.7)	15
4.4	Determination of the layer properties	15
4.5	Rules of the layer concept	26
5	Data concept	27
5.1	Origin points and mating points	27
5.1.1	Rotationally symmetric cutting tool assembly	27
5.1.2	Non-rotationally symmetric cutting tool assembly	28
5.2	Rules for the Layer CUT and NOCUT	30
5.3	Rules for the concept of dimensioning	32
5.3.1	General	32
5.3.2	Cutting tool component	32
5.3.3	Cutting tool combination	33
Annex A (informative)	Examples of the layer structure	34
Bibliography		49