

# DIN EN ISO 6789-1:2017-07 (E)

## Assembly tools for screws and nuts - Hand torque tools - Part 1: Requirements and methods for design conformance testing and quality conformance testing: minimum requirements for declaration of conformance (ISO 6789-1:2017)

---

<b>Contents</b>	<b>Page</b>
European foreword .....	3
Foreword .....	4
Introduction .....	5
<b>1 Scope</b> .....	<b>6</b>
<b>2 Normative references</b> .....	<b>6</b>
<b>3 Terms, definitions and symbols</b> .....	<b>6</b>
3.1 Terms and definitions .....	6
3.2 Symbols, designations and units .....	8
<b>4 Classification</b> .....	<b>8</b>
<b>5 Requirements</b> .....	<b>8</b>
5.1 Design conformance testing .....	8
5.1.1 General .....	8
5.1.2 Maximum torque values .....	9
5.1.3 Specified torque range .....	9
5.1.4 Scales, dials and displays .....	9
5.1.5 Maximum permissible deviation .....	10
5.1.6 Overloading test .....	10
5.1.7 Endurance test .....	10
5.1.8 Effect of geometric changes .....	11
5.2 Quality conformance testing .....	12
5.3 Conformance test during use .....	12
<b>6 Torque measurement</b> .....	<b>12</b>
6.1 Torque measurement system .....	12
6.2 Application of torque .....	13
6.3 Ambient conditions .....	13
6.4 Measurement requirements .....	14
6.5 Measurement sequence .....	16
6.5.1 General .....	16
6.5.2 Indicating torque tools, Type I .....	16
6.5.3 Setting torque tools, Type II .....	16
<b>7 Calculation of deviation</b> .....	<b>17</b>
7.1 General .....	17
7.2 Calculation example 1 .....	17
7.3 Calculation example 2 .....	18
<b>8 Declaration of conformance</b> .....	<b>19</b>
<b>9 Marking</b> .....	<b>19</b>
<b>Annex A (normative) Examples of indicating torque tools (Type I)</b> .....	<b>21</b>
<b>Annex B (normative) Examples of setting torque tools (Type II)</b> .....	<b>22</b>
<b>Annex C (informative) Measurement sequence flowchart for torque tools</b> .....	<b>24</b>
<b>Bibliography</b> .....	<b>27</b>