

# DIN EN 847-1:2018-01 (E)

## Tools for woodworking - Safety requirements - Part 1: Milling tools, circular saw blades

---

<b>Contents</b>		<b>Page</b>
European foreword .....		3
Introduction .....		4
<b>1</b>	<b>Scope .....</b>	<b>5</b>
<b>2</b>	<b>Normative references .....</b>	<b>5</b>
<b>3</b>	<b>Terms, definitions, symbols and abbreviations .....</b>	<b>6</b>
<b>3.1</b>	<b>Terms and definitions .....</b>	<b>6</b>
<b>3.2</b>	<b>Symbols and abbreviations for cutting materials .....</b>	<b>11</b>
<b>4</b>	<b>List of significant hazards .....</b>	<b>14</b>
<b>5</b>	<b>Design requirements .....</b>	<b>14</b>
<b>5.1</b>	<b>General requirements for milling tools and circular saw blades .....</b>	<b>14</b>
<b>5.2</b>	<b>Special requirements for milling tools for machines with hand feed .....</b>	<b>22</b>
<b>6</b>	<b>Tool identification .....</b>	<b>28</b>
<b>6.1</b>	<b>Marking of milling tools for integrated feed other than shank mounted tools or integrated tools .....</b>	<b>28</b>
<b>6.2</b>	<b>Marking of milling tools for machines with hand feed other than shank mounted tools or integrated tools .....</b>	<b>28</b>
<b>6.3</b>	<b>Marking of integrated tools .....</b>	<b>28</b>
<b>6.4</b>	<b>Marking of shank mounted tools .....</b>	<b>29</b>
<b>6.5</b>	<b>Marking of tool sets .....</b>	<b>29</b>
<b>6.6</b>	<b>Marking of circular saw blades .....</b>	<b>30</b>
<b>6.7</b>	<b>Marking of cutting parts and deflectors .....</b>	<b>30</b>
<b>7</b>	<b>Information for use .....</b>	<b>31</b>
<b>7.1</b>	<b>General .....</b>	<b>31</b>
<b>7.2</b>	<b>Safe working practice .....</b>	<b>31</b>
<b>7.3</b>	<b>Maintenance of tools .....</b>	<b>32</b>
<b>7.4</b>	<b>Handling .....</b>	<b>32</b>
<b>Annex A (informative) Maintenance and modification of milling tools and related components .....</b>		<b>34</b>
<b>A.1</b>	<b>General .....</b>	<b>34</b>
<b>A.2</b>	<b>Minimum dimensions .....</b>	<b>34</b>
<b>A.3</b>	<b>Retipping, exchange of tips on composite tools and circular saw blades .....</b>	<b>34</b>
<b>A.4</b>	<b>Milling tools marked with MAN .....</b>	<b>34</b>
<b>A.5</b>	<b>Balance of milling tools .....</b>	<b>34</b>
<b>A.6</b>	<b>Marking .....</b>	<b>34</b>
<b>A.7</b>	<b>Information .....</b>	<b>34</b>
<b>Annex B (normative) Palmqvist Toughness Test .....</b>		<b>35</b>
<b>Bibliography .....</b>		<b>36</b>