

ISO 3002-1:1982-08 (E)

Basic quantities in cutting and grinding; Part 1 : Geometry of the active part of cutting tools; General terms, reference systems, tool and working angles, chip breakers

Contents		Page
1	Scope and field of application	1
2	Reference	1
3	General terms	1
3.1	Surfaces on the workpiece	1
3.2	Tool elements	1
3.3	Tool surfaces	1
3.4	Cutting edges	2
3.5	Dimensions	3
3.6	Tool and workpiece motions	8
4	Reference systems	12
4.1	Tool-in-hand system	12
4.2	Tool-in-use system	19
5	Tool and working angles	26
5.1	Tool angles	26
5.2	Working angles	33
5.3	Sign Convention for angles	38
6	Summary of angles	39
7	Chip breaker	42
	Annex : Lists of equivalent terms in French, Russian, German, Italian and Dutch	46