

# DIN EN 15859:2010-08 (E)

## Air Quality - Certification of automated dust arrestment plant monitors for use on stationary sources - Performance criteria and test procedures

---

<b>Contents</b>		<b>Page</b>
Foreword .....		4
<b>0</b>	<b>Introduction .....</b>	<b>5</b>
<b>1</b>	<b>Scope .....</b>	<b>7</b>
<b>2</b>	<b>Normative references .....</b>	<b>7</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>7</b>
<b>4</b>	<b>Symbols and abbreviations .....</b>	<b>12</b>
<b>4.1</b>	<b>Symbols .....</b>	<b>12</b>
<b>4.2</b>	<b>Abbreviations .....</b>	<b>13</b>
<b>5</b>	<b>General requirements .....</b>	<b>14</b>
<b>5.1</b>	<b>Application of performance criteria .....</b>	<b>14</b>
<b>5.2</b>	<b>Ranges to be tested .....</b>	<b>14</b>
<b>5.2.1</b>	<b>General .....</b>	<b>14</b>
<b>5.2.2</b>	<b>Certification range for filter dust monitor .....</b>	<b>14</b>
<b>5.2.3</b>	<b>Supplementary ranges for filter dust monitors .....</b>	<b>14</b>
<b>5.2.4</b>	<b>Type of arrestment plant for filter leakage monitors .....</b>	<b>14</b>
<b>5.2.5</b>	<b>Expression of performance criteria with respect to ranges .....</b>	<b>15</b>
<b>5.2.6</b>	<b>Ranges of optical in-situ instrument with variable optical length (cross-stack) .....</b>	<b>15</b>
<b>5.3</b>	<b>Manufacturing consistency and changes to instrument design .....</b>	<b>15</b>
<b>5.4</b>	<b>Qualifications of test laboratories .....</b>	<b>15</b>
<b>6</b>	<b>Performance characteristics for laboratory testing .....</b>	<b>15</b>
<b>6.1</b>	<b>Instrument for testing .....</b>	<b>15</b>
<b>6.2</b>	<b>CE labelling .....</b>	<b>15</b>
<b>6.3</b>	<b>Security .....</b>	<b>16</b>
<b>6.4</b>	<b>Output ranges and zero-point .....</b>	<b>16</b>
<b>6.5</b>	<b>Additional outputs on filter leakage monitors .....</b>	<b>16</b>
<b>6.6</b>	<b>Display of operational status signals .....</b>	<b>16</b>
<b>6.7</b>	<b>Degrees of protection provided by enclosures .....</b>	<b>16</b>
<b>6.8</b>	<b>Response time .....</b>	<b>16</b>
<b>6.9</b>	<b>Detection time .....</b>	<b>16</b>
<b>6.10</b>	<b>Repeatability standard deviation at automatic internal zero point .....</b>	<b>16</b>
<b>6.11</b>	<b>Repeatability standard deviation at automatic internal reference point .....</b>	<b>17</b>
<b>6.12</b>	<b>Automatic internal zero and reference point checks .....</b>	<b>17</b>
<b>6.13</b>	<b>Influence of ambient temperature .....</b>	<b>17</b>
<b>6.14</b>	<b>Influence of sample gas flow for extractive instrument .....</b>	<b>17</b>
<b>6.15</b>	<b>Influence of voltage variations .....</b>	<b>17</b>
<b>6.16</b>	<b>Influence of vibration .....</b>	<b>17</b>
<b>6.17</b>	<b>Cross-sensitivity .....</b>	<b>17</b>
<b>6.18</b>	<b>Excursion of measurement beam of cross-stack in situ instruments .....</b>	<b>18</b>
<b>6.19</b>	<b>Detection limit .....</b>	<b>18</b>
<b>7</b>	<b>Performance characteristics for field testing .....</b>	<b>18</b>
<b>7.1</b>	<b>Calibration function for filter dust monitors .....</b>	<b>18</b>
<b>7.2</b>	<b>Functional test of filter leakage monitor .....</b>	<b>18</b>
<b>7.2.1</b>	<b>General .....</b>	<b>18</b>

7.2.2	Plant failure detection test .....	18
7.2.3	Simulated filter failure test .....	19
7.3	Maintenance interval .....	19
7.4	Drift of automatic internal zero point and automatic internal reference point .....	19
7.5	Availability .....	19
7.6	Reproducibility .....	19
8	Performance criteria .....	19
9	General test requirements .....	21
10	Test procedures for laboratory tests .....	22
10.1	Instrument for testing .....	22
10.2	CE labelling .....	22
10.3	Security .....	22
10.4	Output ranges and zero point .....	23
10.5	Additional outputs on filter leakage monitors .....	23
10.6	Display of operational status signals .....	23
10.7	Degrees of protection provided by enclosures .....	23
10.8	Response time .....	23
10.9	Detection time .....	25
10.10	Repeatability standard deviation at automatic internal zero and reference points .....	25
10.11	Influence of ambient temperature .....	25
10.12	Influence of sample gas flow for extractive instruments .....	26
10.13	Influence of voltage variations .....	27
10.14	Influence of vibration .....	28
10.15	Cross-sensitivity .....	29
10.16	Excursion of measurement beam of cross-stack in situ instruments .....	29
10.17	Detection limit .....	29
11	Requirements for field tests .....	30
11.1	Provisions .....	30
11.2	Field test duration .....	30
12	Test procedures for field tests .....	30
12.1	Calibration function for filter dust monitor .....	30
12.2	Functional test of filter leakage monitor .....	31
12.2.1	Plant failure detection test .....	31
12.2.2	Simulated filter failure test .....	31
12.3	Maintenance interval .....	31
12.4	Drift of automatic internal zero point and automatic internal reference point .....	32
12.5	Availability .....	32
12.6	Reproducibility .....	33
13	Test report .....	35
	Annex A (informative) Elements of recommended performance testing report .....	36
	Bibliography .....	38