

# ISO 16000-27:2014-06 (E)

## Indoor air - Part 27: Determination of settled fibrous dust on surfaces by SEM (scanning electron microscopy) (direct method)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		vi
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Symbols and abbreviations .....	3
4.1	Symbols .....	3
4.2	Abbreviations .....	4
5	Principle .....	4
6	Apparatus and material .....	4
6.1	Equipment and materials for adhesive tape sampling and preparation .....	4
6.2	Equipment and material for analysis .....	5
7	Sampling .....	5
7.1	Measurement planning .....	5
7.2	Measurement objectives and sampling sites .....	6
7.3	Number of samples .....	7
7.4	Requirements on the sampled surface .....	8
7.5	Sampling procedure .....	8
7.6	Sampling record .....	9
8	Analysis (SEM) .....	10
8.1	Adjustment of the SEM .....	10
8.2	Procedure .....	10
8.3	Fibre classification by EDXA .....	13
9	Calculation and presentation of results .....	19
10	Record of analysis .....	20
11	Measurement uncertainty .....	20
11.1	General .....	20
11.2	Random sample related deviation .....	21
11.3	Deviations in analysis and weighting of the count results .....	21
11.4	Detection limit .....	21
12	Applications and instructions for use .....	22
12.1	General .....	22
12.2	Sample requirements .....	22
12.3	Summary of the results for multiple individual samples .....	23
Annex A (informative) Example of SEM structure counting form .....		24
Annex B (normative) Procedures for calibration and adjustment of the SEM .....		25

<b>Annex C (informative) Random sample related deviation .....</b>	<b>26</b>
<b>Annex D (informative) Example: using the method in an indoor environment .....</b>	<b>30</b>
<b>Bibliography .....</b>	<b>32</b>