

DIN EN 17628:2022-06 (E)

Fugitive and diffuse emissions of common concern to industry sectors - Standard method to determine diffuse emissions of volatile organic compounds into the atmosphere

Contents		Page
European foreword		7
Introduction		8
1	Scope	9
2	Normative references	9
3	Terms and definitions	9
4	Symbols and abbreviations	12
5	Principle	12
6	Measurement objectives	13
6.1	General	13
6.2	Quantification of site emissions	14
6.3	Quantification of section emissions	14
6.4	Quantification of main equipment emissions	14
6.5	Localization emission sources/leaks	15
7	Data quality objectives	15
7.1	General	15
7.2	Quantification of site emissions	15
7.3	Quantification of section emissions	16
7.4	Quantification of main equipment emissions	16
7.5	Detection/localization of emission sources	16
8	Overview of methods	16
8.1	Applicability and limitations of monitoring techniques	16
8.1.1	Applicability	16
8.1.2	Limitations	17
8.2	Specific methods	19
8.2.1	General	19
8.2.2	Differential Absorption Lidar (DIAL)	19
8.2.3	Solar Occultation Flux (SOF)	21
8.2.4	Tracer Correlation (TC)	23
8.2.5	Optical Gas Imaging (OGI)	25
8.2.6	Reverse Dispersion Modelling (RDM)	27
9	Meteorology data and measurements	29
10	Measurement strategy and measurement campaign planning	30
10.1	General	30
10.2	Measurement objectives	31
10.3	Measurement planning	32
10.3.1	Specification of measurement plan	32
10.3.2	Surveyed areas and equipment	32
10.3.3	Technical supervisor and personnel	32

10.3.4	Planning of the measurement dates	32
10.3.5	Planning of combined measurements	33
10.4	Preparation of the measurement campaign	33
10.4.1	Preparations by the plant operator	33
10.4.2	Preparations by the measurement provider	33
10.4.3	Preparations after arrival at the plant	34
10.5	Conducting the measurements	34
10.6	Calculation of results and measurement uncertainty	34
10.6.1	Calculation of results	34
10.6.2	Assessment of measurement uncertainty	34
10.7	Meteorology	39
11	Reporting	40
12	Results of the validation and demonstration field studies	41
12.1	General	41
12.2	First campaign: validation study	41
12.3	Second campaign: demonstration of the applicability of the methods	42
Annex A (normative) DIAL procedure		43
A.1	Performance requirements	43
A.2	Application of the method	44
A.2.1	Before campaign	44
A.2.2	Set-up and initial tasks	45
A.2.3	Daily tasks	46
A.2.4	Measurement strategy	47
A.3	Quality control	49
A.3.1	General	49
A.3.2	Spectroscopic calibration procedures	49
A.3.2.1	General	49
A.3.2.2	Calibration gases	49
A.3.2.3	Calibration cell	50
A.3.2.4	Spectral scans	50
A.3.2.5	Continuous spectral monitoring	50
A.3.2.6	Check of system performance	50
A.3.3	Meteorological sensors calibration	50
A.4	Data analysis	50
A.4.1	General	50
A.4.2	Background subtraction	50
A.4.3	Normalization for variation in transmitted energy	51
A.4.4	Calculation of path-integrated concentration	51
A.4.5	Derivation of range-resolved concentrations	51
A.4.6	Calculation of emission rates	51
A.5	Reporting	52
Annex B (normative) SOF procedure		53
B.1	Performance requirements	53
B.2	Application of the method	53
B.2.1	Before campaign	53
B.2.2	Set-up and initial tasks	54
B.2.3	Daily tasks	55
B.2.4	Measurement strategy	55
B.3	Quality control	57
B.3.1	General	57
B.3.2	Spectroscopic calibration procedures	57
B.3.2.1	General	57
B.3.2.2	Calibration	57
B.3.3	Meteorological sensors calibration	57
B.3.4	Required QC checks in the field	57
B.4	Data analysis	58

B.4.1	General	58
B.4.2	Calculation of column values	59
B.4.3	Calculation of emission rates	59
B.4.4	Estimation and localization of emission sources	60
B.4.5	Data validation procedures	61
B.5	Reporting	62
Annex C (normative) OGI procedure		63
C.1	Application of the method	63
C.1.1	General	63
C.1.2	Set-up, initial tasks and detection planning	63
C.1.3	Performance of the survey	64
C.2	Quality control	66
C.2.1	Test procedures	66
C.2.1.1	General	66
C.2.1.2	Basic requirements	66
C.2.1.3	Frequency	66
C.2.1.4	Operating mode	66
C.3	Data analysis	67
C.3.1	General	67
C.3.2	Database Management	67
C.3.3	Emission rate calculation and quantification	67
C.4	Reporting	67
C.4.1	General	67
C.4.2	Customer requirements	67
Annex D (normative) TC procedure		68
D.1	Performance requirements	68
D.2	Application of the method	68
D.2.1	Before campaign	68
D.2.2	Set-up and initial tasks	69
D.2.3	Daily tasks	70
D.2.4	Measurement strategy	70
D.3	Quality control	72
D.3.1	General	72
D.3.2	Calibration of gas sensors	72
D.3.3	Meteorological sensor calibration	72
D.3.4	Tracer release equipment calibration	72
D.3.5	Required QC checks in the field	72
D.4	Data analysis	73
D.4.1	Calculation of emission rates	73
D.4.2	Estimation and localization of emission sources	73
D.4.3	Data validation procedures	73
D.5	Reporting	75
Annex E (normative) RDM procedure		76
E.1	General	76
E.2	Performance requirements	76
E.3	Application of the method	77
E.3.1	Before campaign	77
E.3.2	Set-up and initial tasks	78
E.3.3	Daily Tasks	78
E.3.4	Measurement strategy	79
E.4	Quality control	81
E.4.1	General	81
E.4.2	Analyser calibration procedures	81
E.4.2.1	General	81
E.4.2.2	Calibration gases	81
E.4.2.3	Calibration bag	81

E.4.2.4	Continuous monitoring	82
E.4.2.5	Check of system performance	82
E.4.3	Meteorological sensor calibration	82
E.5	Data analysis	82
E.5.1	General	82
E.5.2	Background subtraction	82
E.5.3	Concentration conversion according to speciation	82
E.5.4	Calculation of emission rates	83
Annex F (informative) Meteorology		84
F.1	General	84
F.2	Principles of placement specific to the application on complex sites	85
F.3	Height(s)	86
F.4	Instrumentation choices for wind speed and direction	87
F.5	Performance requirements for wind speed and direction	87
F.6	Lidar profiles	88
F.7	Emission rate calculations	88
F.8	Averaging time suited to different measurement strategies	89
F.9	Spatial variation (physical separation of wind measurement and concentration measurement)	91
F.10	Accounting for low wind speed and atmospheric stability	92
F.11	Instrumentation choices for other relevant data (insolation, temperature, visibility, rain, time-reference)	94
F.11.1	General	94
F.11.2	Time reference	94
F.11.3	Measurement of atmospheric pressure	94
F.11.4	Measurement of air temperature	94
F.11.5	Measurement of the moisture content of air	94
F.11.6	Quality assurance	95
F.12	Reporting	95
Annex G (informative) Example of measurement uncertainty calculation		96
Bibliography		99