

DIN EN 15267-4:2024-09 (E)

Air quality - Assessment of air quality monitoring equipment - Part 4: Performance criteria and test procedures for portable automated measuring systems for periodic measurements of emissions from stationary sources

| Contents | | Page |
|-------------------------|---|-------------|
| European foreword | | 5 |
| Introduction | | 7 |
| 1 | Scope | 10 |
| 2 | Normative references | 10 |
| 3 | Terms and definitions | 10 |
| 4 | Symbols and abbreviations | 18 |
| 5 | General requirements | 20 |
| 5.1 | Application of performance criteria | 20 |
| 5.2 | Ranges to be tested | 21 |
| 5.2.1 | Certification range | 21 |
| 5.2.2 | Supplementary ranges | 21 |
| 5.2.3 | Lower limit of ranges | 22 |
| 5.2.4 | Expression of performance criteria with respect to ranges | 22 |
| 5.2.5 | Ranges of optical in situ P-AMS with variable optical length | 22 |
| 5.3 | Performance testing of P-AMS based on certified AMS previously tested according to EN 15267-3 | 22 |
| 5.4 | Equivalence with the SRM | 22 |
| 5.5 | Manufacturing consistency and changes to P-AMS design | 22 |
| 5.6 | Qualifications of testing laboratories | 22 |
| 6 | Common performance criteria for the laboratory test | 23 |
| 6.1 | P-AMS for testing | 23 |
| 6.2 | Evidence of compliance of legal requirements | 23 |
| 6.3 | Output ranges and zero-point | 23 |
| 6.4 | Operational status signals | 23 |
| 6.5 | Degrees of protection provided by enclosures | 23 |
| 6.6 | Response time | 23 |
| 6.7 | Repeatability standard deviation at zero point | 23 |
| 6.8 | Repeatability standard deviation at span point | 24 |
| 6.9 | Lack of fit | 24 |
| 6.10 | Short-term drift at zero point and at span point | 24 |
| 6.11 | Set-up time after transport and influence of ambient temperature | 24 |
| 6.12 | Influence of supply voltage variations | 24 |
| 6.13 | Influence of vibration | 24 |
| 6.14 | Influence of sample gas pressure for in situ P-AMS | 24 |
| 6.15 | Influence of sample gas flow for extractive P-AMS | 25 |
| 6.16 | Cross-sensitivity | 25 |
| 6.17 | Converter efficiency for P-AMS measuring NO _x | 25 |
| 6.18 | Converter efficiency for P-AMS measuring Hg | 25 |
| 6.19 | Response factors for P-AMS measuring TOC | 25 |
| 6.20 | Influences on P-AMS with in-stack sampling chamber | 25 |
| 6.21 | Influences related to storage and transportation | 26 |

| | | |
|---|---|----|
| 7 | Common performance criteria for the field test | 26 |
| 7.1 | Response time | 26 |
| 7.2 | Short-term drift at zero point and at span point | 26 |
| 7.3 | Reproducibility | 26 |
| 8 | Specific performance criteria for measured components | 26 |
| 8.1 | General | 26 |
| 8.2 | P-AMS measuring gaseous measured components | 26 |
| 8.2.1 | Performance criteria | 26 |
| 8.2.2 | P-AMS measuring TOC | 28 |
| 8.2.3 | P-AMS measuring Hg | 29 |
| 8.3 | P-AMS measuring particulate matter | 29 |
| 9 | General test requirements | 30 |
| 10 | Test procedures for the laboratory test | 32 |
| 10.1 | P-AMS for testing | 32 |
| 10.2 | Evidence of compliance of legal requirements | 32 |
| 10.3 | Output ranges and zero point | 32 |
| 10.4 | Operational status signals | 32 |
| 10.5 | Degrees of protection provided by enclosures | 32 |
| 10.6 | Response time | 33 |
| 10.7 | Repeatability standard deviation at zero point | 34 |
| 10.8 | Repeatability standard deviation at span point | 35 |
| 10.9 | Lack of fit | 35 |
| 10.10 | Short-term drift at zero point and at span point | 37 |
| 10.11 | Set-up time after transportation and influence of ambient temperature | 37 |
| 10.12 | Influence of supply voltage variations | 38 |
| 10.13 | Influence of vibration | 39 |
| 10.14 | Influence of sample gas pressure for in situ P-AMS | 39 |
| 10.15 | Influence of sample gas flow for extractive P-AMS | 40 |
| 10.16 | Cross-sensitivity | 41 |
| 10.17 | Converter efficiency for P-AMS measuring NOX | 42 |
| 10.18 | Converter efficiency for P-AMS measuring Hg | 43 |
| 10.19 | Response factors for P-AMS measuring TOC | 43 |
| 10.20 | Influences on P-AMS with in-stack sampling chamber | 44 |
| 10.21 | Influences related to storage and transportation | 44 |
| 11 | Requirements for the field test | 44 |
| 12 | Common test procedures for the field test | 45 |
| 12.1 | Response time | 45 |
| 12.2 | Short-term drift at zero point and at span point | 45 |
| 12.3 | Reproducibility | 46 |
| 13 | Equivalence with the SRM | 46 |
| 14 | Measurement uncertainty | 47 |
| 15 | Test report | 47 |
| Annex A (informative) European standard reference methods (SRM) and reference methods (RM) .. | | 49 |
| Annex B (normative) Minimum requirements for a test bench | | 50 |
| Annex C (normative) Interferents | | 51 |
| Annex D (informative) Example for the determination of the expanded uncertainty | | 52 |
| D.1 | Determination of uncertainty contributions | 52 |
| D.2 | Elements required for the uncertainty determinations | 52 |
| D.3 | Example of an uncertainty calculation for a P-AMS measuring CO | 54 |

| | | |
|-----|---|----|
| D.4 | Determination of uncertainty contributions by use of sensitivity coefficients | 57 |
| | Annex E (normative) Test of linearity | 58 |
| E.1 | Description of the test procedure | 58 |
| E.2 | Establishment of the regression line | 58 |
| E.3 | Calculation of the residuals of the average concentrations | 59 |
| | Annex F (informative) Elements of a performance test report | 60 |
| | Bibliography | 63 |