

# DIN EN 14625:2025-12 (E)

## Ambient air - Standard method for the measurement of the concentration of ozone by ultraviolet photometry

---

<b>Contents</b>		<b>Page</b>
European foreword .....		8
<b>1</b>	<b>Scope .....</b>	<b>9</b>
<b>2</b>	<b>Normative references .....</b>	<b>10</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>10</b>
<b>4</b>	<b>Abbreviated terms .....</b>	<b>16</b>
<b>5</b>	<b>Principle .....</b>	<b>16</b>
5.1	General .....	16
5.2	Measuring principle .....	16
5.3	Type testing .....	17
5.4	Field operation and quality control .....	18
<b>6</b>	<b>Sampling .....</b>	<b>18</b>
6.1	General .....	18
6.2	Sampling location .....	19
6.3	Sampling system .....	19
6.3.1	Construction .....	19
6.3.2	Particle filter .....	19
6.4	Loss of ozone .....	20
6.5	Control and regulation of sample flow rate .....	20
6.6	Sampling pump for the manifold .....	20
<b>7</b>	<b>Analyser equipment .....</b>	<b>20</b>
7.1	General .....	20
7.2	Ultraviolet absorption cell .....	21
7.3	Ultraviolet source lamp .....	21
7.4	UV detector .....	21
7.5	Ozone-specific scrubber .....	21
7.6	Switching valve .....	21
7.7	Temperature indicator .....	22
7.8	Pressure indicator .....	22
7.9	Flow rate indicator .....	22
7.10	Sampling pump for the analyser .....	22
7.11	Internal ozone span source .....	22
7.12	Particle filter .....	22
<b>8</b>	<b>Type testing of ultraviolet photometric ozone analysers .....</b>	<b>22</b>
8.1	General .....	22
8.2	Relevant performance characteristics and performance criteria .....	23
8.3	Design change .....	27
8.4	Procedures for determination of the performance characteristics during the laboratory test .....	27
8.4.1	General .....	27
8.4.2	Test conditions .....	27
8.4.3	Response time .....	29
8.4.4	Short-term drift .....	31
8.4.5	Repeatability standard deviation .....	32

8.4.6	Lack of fit of linearity of the calibration function .....	32
8.4.7	Sensitivity coefficient to sample gas pressure .....	33
8.4.8	Sensitivity coefficient to sample gas temperature .....	34
8.4.9	Sensitivity coefficient to the surrounding temperature .....	34
8.4.10	Sensitivity coefficient to electrical voltage .....	35
8.4.11	Interferents .....	36
8.4.12	Averaging test .....	36
8.4.13	Difference sample/calibration port .....	37
8.4.14	Residence time in the analyser .....	38
8.5	Determination of the performance characteristics during the field test .....	38
8.5.1	General .....	38
8.5.2	Selection of a monitoring station for the field test .....	38
8.5.3	Operational requirements .....	39
8.5.4	Long-term drift .....	40
8.5.5	Reproducibility standard deviation under field conditions .....	40
8.5.6	Period of unattended operation .....	41
8.5.7	Period of availability of the analyser .....	41
8.6	Type testing and uncertainty calculation .....	42
9	Field operation and ongoing quality control .....	42
9.1	General .....	42
9.2	Suitability evaluation .....	43
9.2.1	General .....	43
9.2.2	Analyser for a monitoring station or task .....	43
9.3	Initial installation .....	44
9.4	Ongoing quality assurance/quality control .....	46
9.4.1	General .....	46
9.4.2	Frequency of calibrations, checks and maintenance .....	47
9.5	Calibration of the analyser .....	50
9.5.1	General .....	50
9.5.2	Calibration gases .....	51
9.5.3	Data adjustment function .....	51
9.5.4	Testing the sampling system .....	51
9.5.5	Treatment of data after exceedance of performance criteria .....	53
9.6	Checks .....	55
9.6.1	Zero and span checks .....	55
9.6.2	Lack of fit .....	56
9.6.3	Testing the sample manifold .....	57
9.7	Maintenance .....	58
9.7.1	Change of particle filters .....	58
9.7.2	Maintenance of sampling system .....	58
9.7.3	Change of consumables as applicable .....	58
9.7.4	Preventive/routine maintenance of components of the analyser .....	58
9.8	Data handling and data reports .....	59
9.9	Measurement uncertainty .....	59
10	Expression of results .....	59
11	Test reports and documentation .....	60
11.1	Type testing .....	60
11.2	Field operation .....	61
11.2.1	Suitability evaluation .....	61
11.2.2	Documentation .....	61
11.2.3	Ambient air quality data reports .....	61
Annex A (normative)	Test of lack of fit .....	63
A.1	Establishment of the regression line .....	63
A.2	Calculation of the residuals of the averages .....	64
Annex B (informative)	Sampling equipment .....	65

<b>Annex C (informative) Ultraviolet photometric analyser</b>	<b>67</b>
<b>Annex D (informative) Manifold testing</b>	<b>69</b>
D.1 Procedure for applying test gas	69
D.2 Procedure for the cross test	70
D.2.1 General	70
D.2.2 Initial stage	70
D.2.3 Stage 1	71
D.2.4 Stage 2	71
D.2.5 Data Processing	71
D.2.6 Evaluation	71
<b>Annex E (normative) Type testing</b>	<b>73</b>
E.1 Type testing and uncertainty calculation	73
E.1.1 Type testing	73
E.1.2 Uncertainty calculation	73
E.2 Type testing Requirement a)	73
E.3 Type testing Requirement b)	75
E.3.1 General	75
E.3.2 Calculation of standard uncertainties	78
E.3.2.1 General	78
E.3.2.2 Repeatability at zero	78
E.3.2.3 Repeatability at the hourly alert threshold value of ozone	78
E.3.2.4 Lack of fit	79
E.3.2.5 Influence quantities	79
E.3.2.5.1 General	79
E.3.2.5.2 Sample gas pressure	80
E.3.2.5.3 Sample gas temperature	80
E.3.2.5.4 Surrounding temperature	80
E.3.2.5.5 Electrical voltage	81
E.3.2.5.6 Water vapour	81
E.3.2.5.7 Other interferences	82
E.3.2.5.8 Averaging effect	83
E.3.2.5.9 Calibration gas	83
E.3.2.5.10 Difference sample/calibration port	83
E.3.3 Example calculation	84
E.4 Type testing Requirement c)	85
E.5 Type testing Requirement d)	85
E.5.1 General	85
E.5.2 Combined standard uncertainty	87
E.5.3 Absolute expanded uncertainty	87
E.5.4 Relative expanded uncertainty	87
E.5.5 Calculation of standard uncertainties	88
E.5.6 Example calculation	90
<b>Annex F (informative) Calculation of uncertainty in field operation at the hourly alert threshold value</b>	<b>92</b>
F.1 General	92
F.2 Combined standard uncertainty	92
F.3 Standard uncertainties	93
F.3.1 General	93
F.3.1.1 Introduction	93
F.3.1.2 Repeatability at zero	93
F.3.1.3 Repeatability at the hourly alert threshold value	93
F.3.1.4 Lack of fit	93
F.3.2 Influence quantities	94
F.3.2.1 General	94
F.3.2.2 Sample gas pressure	94
F.3.2.3 Sample gas temperature	94

F.3.2.4	Surrounding temperature .....	95
F.3.2.5	Electrical voltage .....	96
F.3.3	Interferents .....	96
F.3.3.1	General .....	96
F.3.3.2	Water vapour .....	96
F.3.3.3	Other interferents .....	97
F.3.4	Averaging effect .....	97
F.3.5	Reproducibility under field conditions .....	97
F.3.6	Long-term drift at zero .....	97
F.3.7	Long-term drift at level of the hourly alert threshold value .....	98
F.3.8	Zero gas .....	98
F.3.9	Calibration gas .....	98
F.3.10	Difference sample/calibration port .....	98
F.4	Example calculation .....	99
<b>Annex G (informative) Calculation of uncertainty in field operation at the 8-hour target value .....</b>		<b>101</b>
G.1	General .....	101
G.2	Combined standard uncertainty .....	101
G.3	Standard uncertainties .....	102
G.3.1	General .....	102
G.3.1.1	Introduction .....	102
G.3.1.2	Repeatability at zero .....	102
G.3.1.3	Repeatability at the 8-hour target value .....	103
G.3.1.4	Lack of fit .....	103
G.3.2	Influence quantities .....	103
G.3.2.1	General .....	103
G.3.2.2	Sample gas pressure .....	104
G.3.2.3	Sample gas temperature .....	104
G.3.2.4	Surrounding temperature .....	105
G.3.2.5	Electrical voltage .....	105
G.3.3	Interferents .....	106
G.3.3.1	General .....	106
G.3.3.2	Water vapour .....	106
G.3.3.3	Other interferents .....	107
G.3.4	Averaging effect .....	108
G.3.5	Zero gas .....	108
G.3.6	Calibration gas .....	108
G.3.7	Difference sample/calibration port .....	108
G.3.8	Reproducibility under field conditions .....	108
G.3.9	Long-term drift at zero .....	109
G.3.10	Long-term drift at level of the 8-hour target value .....	109
G.4	Example calculation .....	110
<b>Annex H (informative) Test stand for the test point "sensitivity coefficient of sample gas pressure" .....</b>		<b>112</b>
<b>Annex I (informative) Significant changes .....</b>		<b>113</b>
<b>Bibliography .....</b>		<b>114</b>