

# DIN EN 1948-3:2006-06 (E)

## Stationary source emissions - Determination of the mass concentration of PCDDs/PCDFs and dioxin-like PCBs - Part 3: Identification and quantification of PCDDs/PCDFs

---

<b>Contents</b>	<b>Page</b>
Foreword .....	3
Introduction .....	6
1 Scope .....	7
2 Normative references .....	7
3 Terms and definitions .....	7
4 Symbols and abbreviations .....	10
5 Principles of identification and quantification .....	11
6 Reagents, materials and equipment .....	11
7 Safety measures .....	11
8 Quality control requirements for identification and quantification .....	11
9 Quality assurance criteria for extraction/clean-up/quantification procedure blanks .....	13
10 Calibration of the HRGC/HRMS .....	14
11 Quantification of HRGC/HRMS results .....	15
12 Calculation of the measurement results .....	18
13 Analytical report .....	18
14 Performance characteristics .....	19
15 Interferences .....	21
Annex A (informative) Examples of operation of gas chromatography / mass spectrometry analysis of PCDDs/PCDFs in emission samples .....	22
Annex B (informative) Estimation of the measuring uncertainty and precision of the determination of polychlorinated dibenzo-p-dioxins and dibenzofurans .....	31
Annex C (informative) Mass of ions monitored for PCDDs and PCDFs .....	35
Annex D (informative) Relative abundance of chlorine isotope ions and their ratio for PCDD/PCDF congeners containing 4 to 8 chlorine substituents .....	36
Annex E (informative) Further general recommendations for separation, detection and quantification of PCDDs/PCDFs .....	37
Annex F (informative) Variability determination based on the results of the validation tests .....	39
Annex G (informative) Relation to EU Directives .....	47
Bibliography .....	48