

DIN EN ISO 19403-2:2024-11 (E)

Paints and varnishes - Wettability - Part 2: Determination of the surface free energy of solid surfaces by measuring the contact angle (ISO 19403-2:2024)

| Contents | | Page |
|-------------------------------------------------------------------------|-------|-------------|
| European foreword | | 3 |
| Foreword | | 4 |
| 1 Scope | | 5 |
| 2 Normative references | | 5 |
| 3 Terms and definitions | | 5 |
| 4 Principle | | 5 |
| 5 Apparatus and materials | | 6 |
| 6 Sampling | | 7 |
| 7 Procedure | | 7 |
| 7.1 General for measuring on the horizontal drop | | 7 |
| 7.1.1 Setting up the contact angle measuring system | | 7 |
| 7.1.2 Test conditions | | 8 |
| 7.1.3 Conditioning of the test panels | | 8 |
| 7.2 Measurement | | 8 |
| 7.2.1 General | | 8 |
| 7.2.2 Static method | | 8 |
| 7.2.3 Dynamic method (progressive contact angle) | | 9 |
| 7.2.4 Determination of the contact angle | | 10 |
| 8 Evaluation | | 10 |
| 8.1 General | | 10 |
| 8.2 Owens-Wendt-Rabel-Kaelble method (OWRK method) | | 10 |
| 8.3 Wu method | | 11 |
| 9 Precision | | 12 |
| 9.1 General | | 12 |
| 9.2 Repeatability limit, <i>r</i> | | 12 |
| 9.3 Reproducibility limit, <i>R</i> | | 12 |
| 9.4 Calculation in accordance with the Owens-Wendt-Rabel-Kaelble method | | 12 |
| 10 Test report | | 13 |
| Annex A (informative) Notes on measuring practice | | 14 |
| Bibliography | | 18 |