

# DIN EN ISO 8502-6:2006-10 (E)

Preparation of steel substrates before application of paints and related products -  
Tests for the assessment of surface cleanliness - Part 6: Extraction of soluble  
contaminants for analysis - The Bresle method (ISO 8502-6:2006)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		2
Introduction .....		4
1	Scope .....	5
2	Normative references .....	5
3	Principle .....	5
4	Apparatus and materials .....	6
5	Procedure .....	6
6	Test report .....	7
Annex A (normative) Leak test for type testing of patches .....		10