

# ISO 22476-11:2017-04 (E)

## Geotechnical investigation and testing - Field testing - Part 11: Flat dilatometer test

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms, definitions and symbols .....</b>	<b>1</b>
3.1	Terms and definitions .....	1
3.2	Symbols .....	4
<b>4</b>	<b>Equipment .....</b>	<b>4</b>
4.1	Dilatometer equipment .....	4
4.2	Insertion apparatus .....	6
<b>5</b>	<b>Test procedure .....</b>	<b>7</b>
5.1	Maintenance and checks .....	7
5.2	Membrane calibration procedure .....	8
5.3	Flat dilatometer test .....	8
5.3.1	Operations before testing .....	8
5.3.2	Basic test procedure .....	8
5.3.3	C-pressure readings .....	9
5.3.4	Operations after testing .....	9
5.4	DMT dissipation test (DMTA) .....	9
5.5	DMT short dissipation test (DMTA-s) .....	9
5.6	Safety requirements .....	10
<b>6</b>	<b>Test results .....</b>	<b>10</b>
<b>7</b>	<b>Report .....</b>	<b>11</b>
7.1	General .....	11
7.2	Reporting of test results .....	11
7.2.1	General information .....	11
7.2.2	Location of sounding .....	12
7.2.3	Test equipment .....	12
7.2.4	Test procedure .....	13
7.2.5	Test results .....	13
7.3	Presentation of results .....	13
<b>Annex A (informative) Example interpretation formulae .....</b>		<b>15</b>
<b>Bibliography .....</b>		<b>17</b>